





WP4

Platy limestone as cultural heritage Supplement 3.1

Cultural heritage and limestone

Filip Bubalo, Neža Čebron Lipovec, Radoslav Dodig, Mitja Guštin, Branko Orbanić, Fabiana Pieri, Silvije Pranjić, Božidar Premrl, Ana Šverko, Aleksandra Torbica, Ivo Vojnović, Tea Zubin Ferri

Mitja Guštin, Katarina Šmid (eds.)

Annex 3.1.3 Show cases

February 2015







1. »Kraška hiša«/karst house museum, Rupingrande/Repen 31, Monrupino/Repentabor (Trieste), Italy

| RoR description number | ITALIAN KARST 1001 |
|-------------------------------|---|
| | |
| CULTURAL HERITAGE | |
| Name (official and common): | »kraška hiša«/karst house museum |
| Address (location): | Rupingrande/Repen 31, Monrupino/Repntabor (Trieste), Italy |
| Cadastral number, | pcn 34/1, FM 11 CC Rupingrande, PT 666 ct 1 |
| community: | |
| Coordinates: | 45° 43' 28"N – 13° 47' 29"E / 405989E – 5064146N |
| Owner / contact: | Owner: CARSO NOSTRO – NAŠ KRAS – Soc. Coop. a.r.l.; phone 0039-040327240, www.kraskahisa.com |
| Heritage status / protection: | Only in regional catalogue (no legal value) A4392 – Museum |
| Use (original): | Till 1968 farm house, later museum. |
| Typology: | One floor farm house with external stone stairs, wooden |
| | gallery, jutting roof and inner fire-place kitchen. |
| Short description | Typical karst home with walled farmyard ("borjač"). It's a |
| (ground plan, architectural | court-yard house with stone portal gate (»kaluna«) and well |
| elements, chronology): | in the court. |
| | Home is visible already on Franciscan cadastral map from 1819 (State Archive of Trieste, signature: 679 b 03). The house, with its agricultural buildings and the "borjac" cannot be precisely dated, but very probably dates back to the end of the XVIII century. Its present appearance dates back to 1831, when the last additions were made and it was renovated. Subsequent building work was exclusively aimed at its conservation. The NAŠ KRAS cooperative society bought the building on 29.04.1968 and restored the house. The museum opened in september 1968. The project of architect Marjan Loboda from Ljubljana established to put the outside pavement, the cistern and the high yard wall. Some restoration works were done in 1999. |
| Special features: | Preserved original volume and construction, preserved historic arrangement of rooms. The living quarters include the kitchen ("hiša") on the ground floor and, on the upper floor, the bedroom and the loft "na podu", where often the older members of the family or the children used to sleep, although the use of this room was twofold: in fact, agricultural produce, such as wheat, barley, potatoes and walnuts was also kept in it. The kitchen is paved with a chiseled stone floor, a large part of it being occupied by the raised hearth, which is open, typical of the Mediterranean style, overhung by the hood ("napa"), with its characteristic wooden shelving and decorative curtain around the hood |

| Platy limestone in elements / state of conservation: | ("tornakamin"). Next to the hearth we also find the wooden oven. The karstic kitchen has two characteristic niches, one next to the window and another in the wall ("škafenca") with a shelf for vased and a water container. The crockery and the utensils on display are all original. The same is true for the interiors of all the rooms, such as the bedroom, where next to the small double bed ("za poldrugo peršono") we find the typical cot and, next to the wall, there is the karstic bottom drawer. On the bed we can see the characteristic mattress of maize husks ("Iubenca"). In the farm buildings (the cellar – "hram" / the stables – "stala" / the loft – "na podu"), the visitor will see the activities of the karst inhabitants of the past which enabled them to survive; the tools and objects on display represent a cross-section of some of the more frequent occupations: viticulture, animal husbandry, agriculture. The old hayloft – "na štali" located above the stable is nowadays used as a space for temporary exhibitions. In the courtyard there is also the shed - skedenj, in which the paesant trimmed and sorted his produce collected from the fields. The carriage and several other agricultural implements were also kept in the shed. Under the stairs there was the pig-sty. The Roofs of the main part, pavement (inside »škrle«; outside »šeliž«), roof cornice and roof of portal gate. The roof, wooden gallery and northern façade need some |
|--|--|
| Notes: | restoration works. |
| Descriptor: | Fabiana Pieri |
| Date of fieldwork: | 30.06.2013 – 20.03.2014 - 2.5.2014 |
| | |
| GEOLOGY | |
| Selected limestone elements: | 1 main roof: Repen limestone (Aurisina Limestone Formation) 2 roof of portal gate: Repen limestone (Aurisina Limestone Formation) 3 roof cornice: Repen limestone (Aurisina Limestone Formation) 4 gallery shelves: Repen limestone (Aurisina Limestone Formation) 5 corner stones: Repen limestone (Aurisina Limestone Formation) 6a window frame (stable): Repen limestone (Aurisina Limestone Formation) 6b window frame: Repen limestone (Aurisina Limestone Formation) 7a doorpost: Repen limestone (Aurisina Limestone Formation) 7b doorpost (kitchen): Repen limestone (Aurisina Limestone Formation) 7c doorpost (portal gate): Repen limestone (Aurisina |

| | Limestone Formation) |
|------------------------------|--|
| | 8 stairs: Repen limestone (Aurisina Limestone Formation) |
| | 9 inside pavement: Repen limestone (Aurisina Limestone |
| | Formation) |
| | 10 outside pavement: Repen limestone (Aurisina Limestone |
| | Formation) |
| Quarries/excavation sites in | Quarries in the Monrupino municipality (Zolla, Repen, |
| neighbourhood: | Sagrado). |
| | The stones for the roof restoring come from an abandoned |
| | quarry located South from Repen village. |
| Notes: | |
| Descriptor: | Sara Biolchi |
| Datum: | 25.06. 2014 |


Illustrative enclosure to the Roof of Rock description Sheet:

Topographic map, general:



Geopedia.si

Topographic map, local:




CTRN: Monrupino 110080, 1: 10.000 scale

Ortophoto / satellite photo:



Ortophoto cyclic recording 2013



Cadastral plan: pcn 34/1 Rupingrande

Historical maps:



Franciscan cadastral map (1819)

Historical photography:



Situation ca. 1982 (photo: Regional cataloguing center)

Photodokumentation:





















Fieldwork, 30.06.2013 - 20.03.2014 (photo F. Pieri)


Architectural drawings:




Ground floor




first floor





roof plan











Author of architectural drawings: Fabiana Pieri

Description sheet prepared by Fabiana Pieri, Trieste 30. 04. 2014 – updated on 30.06.2014

2. Karst house, Rupingrande/Repen 20, Monrupino/Repentabor (Trieste), Italy


| RoR description number | ITALIAN KARST 1002 |
|--|---|
| CULTURAL HERITAGE | |
| Name (official and common): | karst house |
| Address (location): | Rupingrande/Repen 20, Monrupino/Repentabor (Trieste), Italy |
| Cadastral number, community: | pcn 27, FM 11 CC Rupingrande, PT 1029 ct 1 |
| Coordinates: | 45° 43' 28"N – 13° 47' 27"E / 405962E – 5064121N |
| Owner / contact: | Owner: Provincia di Trieste, Area Servizi tecnici, Unità Operativa Patrimonio Gare e contratti, via S. Anastasio, 3 - 34132 Trieste – arch. Federica Rovello, phone 0039- 040 3798 249, federica.rovello@provincia.trieste.it |
| Heritage status / protection: | Declaration of cultural interest on 29.06.2005, GN 1323 - 1.02.2006 |
| Use (original): | Till 1974 farm house, later headquarters of Consortium for the Protection of the Denomination of wines "Karst" Controlled Origin and exhibition space. |
| Typology: | One floor farm house with external stone stairs, wooden gallery, jutting roof and inner fire-place kitchen. |
| Short description (ground plan, architectural elements, chronology): | Typical karst home with walled farmyard ("borjač"). It's a court-yard house with stone portal gate (»kaluna«). Home is visible already on Franciscan cadastral map from 1819 (State Archive of Trieste, signature: 679 b 03). The house, with its agricultural buildings and the "borjac" cannot be precisely dated, but very probably dates back to the end of the XVIII century. Its present appearance dates back to 1800, when the last addictions were made and it was renovated. The Trieste Province bought the building on 8.03.1974 and restored the house in 1977. |
| Special features: | Its original volume and construction have been preserved, altough the historic arrangement of rooms has not been maintained. The project of architect Giorgio Berni from Trieste, on 1977, established to build the concrete floor behind the portal gate and changed all rooms arrangement. The stone roof has been reconstructed over a brick and concrete roofing. Originally the living quarters include the kitchen ("hiša") on the ground floor and, on the upper floor, the bedroom and the loft "na podu". Under the stairs there was the pig-sty. In the farm buildings there was the cellar – "hram", the stables – "stala" and the loft – "na podu". |
| Platy limestone in elements / state of conservation: | Roofs of main part, roof cornice and portal gate shelf. The wooden gallery need some restoration works, many |
| Notes | elements not related to the house should be removed. |
| Notes: Descriptor: | Fabiana Pieri |
| Date of fieldwork: | 30.06.2013 – 17.04.2014 - 2.5.2014 |
| Dute of fletawork. | JU.UU.201J = 17.U4.2014 - 2.J.2014 |

| GEOLOGY | |
|------------------------------|--|
| Selected limestone elements: | 0 walls: Repen limestone (Aurisina Limestone Formation) |
| Selected untestone elements. | 1 main roof: Repen limestone (Aurisina Limestone |
| | Formation) |
| | 2 roof cornice: Repen limestone (Aurisina Limestone |
| | Formation) |
| | 3 gallery shelves: Repen limestone (Aurisina Limestone |
| | Formation) |
| | 4 corner stones: Repen limestone (Aurisina Limestone |
| | Formation) |
| | 5 window frame: Repen limestone (Aurisina Limestone |
| | Formation) |
| | 6 doorpost (portal gate): Repen limestone (Aurisina |
| | Limestone Formation) |
| | 7 portal gate shelf: Repen limestone (Aurisina Limestone |
| | Formation) |
| | 8 stairs: Repen limestone (Aurisina Limestone Formation) |
| Quarries/excavation sites in | Quarries in the Monrupino municipality (Zolla, Repen, |
| neighbourhood: | Sagrado) |
| Notes: | |
| Descriptor: | Sara Biolchi |
| Datum: | 25.06.2014 |

Topographic map, general:




Topographic map, local:



Ortophoto / satellite photo:




Ortophoto cyclic recording 2013



Cadastral plan: pcn pcn 27 Rupingrande

Historical maps:



Franciscan cadastral map (1819)

Photodokumentation:











Fieldwork, 30.06.2013 - 17.04.2014 (photo F. Pieri)


Architectural drawings:




Ground floor





First floor



Roof plan







Author of architectural drawings: Fabiana PieriDescription sheet prepared by Fabiana Pieri, Trieste 30. 04. 2014, updated on 30.06.2014

3. Ljenčkica's house, Trebiciano 107, Trieste, Italy

| RoR description number | ITALIAN KARST 1003 |
|--|---|
| CULTURAL HERITAGE | |
| Name (official and common): | Ljenčkica's house |
| Address (location): | Trebiciano 107, Trieste, Italy |
| Cadastral number, | pcn 54, FM 8 CC Trebiciano, PT 698 ct 1 |
| community: | |
| Coordinates: | 45° 40' 22"N – 13° 49' 33"E / 408541E – 5058361N |
| Owner / contact: | Owner: Slovensko kulturno drustvo Primorec; phone 0039-040635626, sonia@zskd.eu |
| Heritage status / protection: | Ministerial Decree 06/08/1981 |
| Use (original): | Till 1999 dwelling house, later museum and cultural center. |
| Typology: | It's a typical »single cell« house with added kitchen. |
| Short description (ground plan, architectural elements, chronology): | Typical »single cell« karst home with added kitchen (<i>spahnjenca</i>) and interior oven. Home is visible already on Franciscan cadastral map from 1822 (State Archive of Trieste, signature: 693 a 05). The house cannot be precisely dated, but very probably dates back to the end of the XVIII century. In an 1838 "building protocol" is described as a stable with courtyard ("hlev in dvorišče"). In 1924, according to the "Status animarum" for the Trebiciano parish the family Ljenčkica-Slavec lived in the house. So perhaps it was initially a stable and then, at the end of 1800s was transformed in a dwelling house. The Slovensko kulturno drustvo Primorec bought the building on 1999 and restored the house. |
| Special features: | Preserved original volume and construction. Originally the house had two rooms, a bedroom and the kitchen. Now it has only a room. |
| Platy limestone in elements / | The spahnjenca is covered with skrle both in platy |
| state of conservation: | limestone and sandstone. All well-preserved since recently restored. |
| Notes: | |
| Descriptor: | Fabiana Pieri |
| Date of fieldwork: | 30.06.2013 - 20.03.2014 - 02.05.2014 |
| GEOLOGY | |
| Selected limestone elements: | 0 walls: Repen limestone (Aurisina Limestone Formation) 1 spahnjenca roof: Repen and Aurisina limestone (Aurisina Limestone Fm.) and sandstone (Flysch of Trieste) 2 roof cornice: Aurisina limestone (Aurisina Limestone Formation) 3 corner stones: various types of stones of Aurisina Limestone Formation 4a window frame: Aurisina Fiorita (Aurisina Limestone Formation) |
| | 4b window frame: Alveolinid and Nummulitid Limestone |

| | (Foraminiferal Limestones) |
|------------------------------|--|
| | 5 doorpost: Alveolinid and Nummulitid Limestone |
| | (Foraminiferal Limestones) |
| Quarries/excavation sites in | Repen limestones: quarries in the Monrupino municipality |
| neighbourhood: | (Zolla, Repen, Sagrado) |
| | Aurisina Chiara and Aurisina Fiorita: quarries at Aurisina |
| | Alveolinid and Nummulitid Limestones: there are some |
| | quarries in the south-eastern part of the Trieste Karst, along |
| | the road built at the foot of the Karst edge and in the |
| | municipality of Dolina. |
| Notes: | |
| Descriptor: | Sara Biolchi |
| Datum: | 25.06. 2014 |
| | |


 ${\it Illustrative\ enclosure\ to\ the\ Roof\ of\ Rock\ description\ Sheet:}$

Topographic map, general:



Geopedia.si

Topographic map, local:




CTRN: Trieste NORD 110100, 1: 10.000 scale

Ortophoto / satellite photo:



Ortophoto cyclic recording 2008

Modern cadastral map:



Cadastral plan: pcn 54 Trebiciano

Historical maps:



Franciscan cadastral map (1822)

Historical photography:



1976 (photo: Regional cataloguing center)

Situation ca.

Photodokumentation:











Fieldwork, 30.06.2013 - 20.03.2014 (photo F. Pieri)


Architectural drawings:





Ground floor




Roof plan









Author of architectural drawings: Fabiana Pieri

Description sheet prepared by Fabiana Pieri, Trieste 30. 04. 2014 - updated on 30.06.2014


4. Chiesa di San Rocco e San Sebastiano, Santa Croce 1013, Trieste, Italy

| RoR description number | ITALIAN KARST 1004 |
|--|--|
| CHI THE AL HEDITAGE | |
| Name (official and common): | Saint Rocco and Saint Sebastiano church |
| Address (location): | Santa Croce 1013, Trieste, Italy |
| Cadastral number, | pcn 1702, FM 13 CC Santa Croce, PT 3359 |
| community: | pen 1702, 111 13 ee santa eroee, 1 1 3333 |
| Coordinates: | 45° 43' 55"N – 13° 41' 38"E / 398397E – 5065113N |
| Owner / contact: | Owner: Comune di Trieste, contact: arch. Massimo Mosca +390406754196, mail: MOSCA@comune.trieste.it |
| Heritage status / protection: | National monument – Legislative Decree no. 42/2004 (Pending verification, such properties are provisionally subject to the regulations of the protection provided by the Code) |
| Use (original): | Church |
| Typology: | It's a small simple building following a rectangular plan with a stone belfry above the gateway. |
| Short description | It's a simple small building following a rectangular plan |
| (ground plan, architectural elements, chronology): | with a stone belfry above the gateway. The presbitery has a ribbed vault. Near the gateway there is a stone statue showing a <i>Mendico</i> , made by a local stone mason named Dušak. |
| | It was built in the 17th century (1646), as a vow of escaping Plague. |
| Special features: | Its original volume, construction and historic inner arrangement have been preserved. |
| Platy limestone in elements / state of conservation: | Roof in platy limestone. It has been restored in 1990 involving the placing of a bituminous layer between wooden roofing and <i>skrle</i> and now it has structural problems. It has been shored up. |
| Notes: | |
| Descriptor: | Fabiana Pieri |
| Date of fieldwork: | 30.06.2013 - 05.06.2014 |
| GEOLOGY | |
| Selected limestone elements: | 1 main roof: Aurisina limestone (Aurisina Limestone |
| Second unicione elements. | Formation) 2 corner stones: Aurisina Fiorita (Aurisina Limestone Formation) |
| | 3 window frame: Aurisina Fiorita (Aurisina Limestone Formation) 4 doorpost: Aurisina Fiorita and Chiara(Aurisina Limestone |
| | Formation) 5 stone statue showing a <i>Mendico</i> : Roman Stone or Aurisina Chiara (Aurisina Limestone Formation) 6 ribbed vault: Aurisina Chiara or Fiorita or Granitello (Aurisina Limestone Formation) |

| Quarries/excavation sites in | Aurisina Limestone: quarries close to Santa Croce village |
|------------------------------|---|
| neighbourhood: | Aurisina Fiorita, Aurisina Chiara: quarries at Aurisina |
| | _ |
| Notes: | |
| Descriptor: | Sara Biolchi |
| Datum: | 24 .06. 2014 |
| | |

Illustrative enclosure to the Roof of Rock description Sheet:

Topographic map, general:



Topographic map, local:




CTRN: Sgonico 110050, 1: 10.000 scale

Ortophoto / satellite photo:



Ortophoto cyclic recording 2008

Modern cadastral map:




Cadastral plan: pcn 1702 Santa Croce

Historical maps:




Franciscan cadastral map (1819)

Historical photography:



Situation ca. 1991 (photo: Regional cataloguing center)

Historical drawings:



Municipality archive – 1883

Photodocumentation:
















Fieldwork, 30.06.2013 - 05.06.2014 (photo F. Pieri)


Architectural drawings:




ground floor and roof plan









Author of architectural drawings: Fabiana Pieri

Description sheet prepared by Fabiana Pieri, Trieste 30. 04. 2014 - updated on 30.06.2014

5. Chiesa di Beata Maria Vergine Assunta - community's house, Col, 2 - Monrupino/Repentabor, Trieste, Italy

| ITALIAN KARST 1005 |
|---|
| |
| |
| Assumpsion of the blessed Virgin parish - community's |
| house |
| Col, 2 - Monrupino/Repentabor, Trieste, Italy |
| pcn 110/1, FM 6 CC Rupingrande, PT 96 ct 1 |
| |
| 45° 43' 08"N – 13° 48' 23"E / 407181E – 5063504N |
| Owner: Chiesa parrocchiale della Beata Maria Vergine Assunta/Blažena Devica Marija Vnebovzeta, loc. Col, 2 – 34016 Monrupino/Repentabor (TS) – tel. 040 327118 – 040 211113 |
| monument - Legislative Decree no. 42/2004 Pending verification, such properties are provisionally subject to the regulations of the protection provided by the Code |
| Till 1983 community's house, later monument (used during karst weddings). |
| It's a »single cell« karst building, built on a rock with external stone stairs and interior kitchen fireplace. |
| Typical »single cell« karstie building, built on a rock with |
| external stone stairs. |
| It was built at the beginning of the sixteenth century in |
| response to the Turkish raids on "karst plateau". It was |
| restored rather poorly between 1983 and 1990 and after a |
| few years stone roofs collapsed. The roof have been rebuilt. |
| Original volume and construction have been preserved, |
| historic arrangement of rooms has been preserved too. |
| Roofs of main part. All well preserved since recently |
| restored. |
| |
| Fabiana Pieri |
| 30.06.2013 - 5.6.2014 |
| |
| 0 walls: Repen limestone (Aurisina Limestone Formation) |
| 1 main roof: Repen limestone (Aurisina Limestone Formation) 2 window frame: Repen limestone (Aurisina Limestone Formation) 3 doorpost: Repen limestone (Aurisina Limestone Formation) 4 stairs: Repen limestone (Aurisina Limestone Formation) 5 decorated sitting: Fior di Mare (Aurisina Limestone Formation) |
| |

| | 6 rim of cistern: Repen limestone (Aurisina Limestone Formation) |
|---|--|
| Quarries/excavation sites in neighbourhood: | Repen limestone: quarries in the Monrupino municipality (Zolla, Repen, Sagrado). The stones for the roof restoring come from an abandoned quarry located in Zolla and reused stones from other roofs collapsed. Fior di mare: quarries in the Monrupino municipality, (Rupinpiccolo, Repen) |
| Notes: | |
| Descriptor: | Sara Biolchi |
| Datum: | 24 .06. 2014 |


Illustrative enclosure to the Roof of Rock description Sheet:

Topographic map, general:



Geopedia.si

Topographic map, local:




CTRN: Monrupino 110080, 1: 10.000 scale

Ortophoto / satellite photo:



Ortophoto cyclic recording 2012-2014

Modern cadastral map:



Cadastral plan: pcn 110/1 Rupingrande

Historical maps:




Franciscan cadastral map (1819)


Historical photography:




Situation ca. 1982 (photo: Regional cataloguing center)


Historical drawings:








Friuli Venezia Giulia Superintendence archive – 1989





Friuli Venezia Giulia Superintendence archive – 1989

Photodocumentation:












Fieldwork, 30.06.2013 - 5.6.2014 (photo F. Pieri)

Architectural drawings:



ground floor





Author of architectural drawings: Fabiana Pieri

Description sheet prepared by Fabiana Pieri, Trieste 06. 06. 2014 – updated on 30.06.2014

6. Cerkev sv. Elije, Kopriva, Slovenia

| RoR description number | SLOVENSKI KRAS / SLOVENIAN KARST 2 |
|-------------------------------|---|
| CULTURAL HERITAGE | |
| Name (official and common): | Kopriva, cerkev sv. Elije / church of St. Elias |
| Address (location): | Ropilva, cerkev sv. Enje/ church of St. Enas |
| Cadastral number, | 71/3, c. c. Kopriva |
| community: | 71/5, c. c. Kopriva |
| Coordinates: | Y=409.755, X=71.456 |
| Owner / contact: | RKC; parish of Kopriva |
| | / 1 |
| Heritage status / protection: | spomenik lokalnega pomena (local monument); EŠD: 3780 |
| Use (original): | Church |
| Typology: | The single nave church with a western bell tower |
| Short description | |
| (ground plan, architectural | Building of the single nave church with 3/8 presbytery |
| elements, chronology): | in late baroque style begun in 1802 and ended in 1823 |
| | (constructor Matija Gulič). Bell tower added in 1852-53. |
| | Main altar from 1751, pulpit from 1 st half of 19 th c. |
| Special features: | Inside the church »paleontological museum« |
| Platy limestone in elements / | Roof of presbytery covered with skrle. |
| state of conservation: | All in good state of preservation. |
| Notes: | V |
| Descriptor: | Neža Čebron Lipovec, Mitja Guštin, Božo Premrl |
| Date of fieldwork: | 4.6.2013 |
| GEOLOGY | |
| limestone elements: | 0 walls |
| | 1 main roof |
| | 3 stone bordure |
| | 5 corner stones |
| | 6 window frame |
| | 7 doorpost |
| | 8 bell tower |
| | 8a vault of bell tower |
| | 9 altar |
| | 10 pulpit |
| | 11 balustrada |
| | 12 inside pilars |
| | 13 holy water font |
| | 14 ciborium |
| | 15 inside bordure |
| | 16 stone floor |
| | 17 stone floor |
| | 18 stone floor |
| | 19 stone floor |
| Quarries/excavation sites in | |

| neighbourhood: | |
|----------------|--|
| Notes: | |
| Descriptor: | |
| Datum: | |
| | |


Illustrative enclosure to the Roof of Rock description Sheet:

Topographic map, general:



Geopedia.si

Topographic map, local:



TK 25 (http://rkg.gov.si/GERK)

Ortophoto / satellite photo:




Ortophoto cyclic recording 2012-2014 (http://gis.arso.gov.si/atlasokolja)

Modern cadastral map:



71/3, c. c. Kopriva (http://rkg.gov.si/GERK)

Historical maps:



Franciscan cadastral map (situla.org)

Historical photography:





1982, source: ZVKDS

Photo documentation:



Fieldwork, 18.5.2013 (photo N. Čebron)



Fieldwork, 18.5.2013 (photo N. Čebron)










Fieldwork, 18.5.2013 (photo N. Čebron)







13 14 15









18 19


7. Cerkev Marijinega vnebovzetja, Šmarje pri Sežani, Slovenia

| Assumption of Mary Smarje pri Sežani Cadastral number, community: Coordinates: V= 412.165, X= 64.817 RKC; contact: parish priest Sandi Škapin from Sežana Heritage status / protection: Spomenik lokalnega pomena (local monument); EŠD: 746 Use (original): Typology: Short description (ground plan, architectural elements, chronology): The single nave Karstic church The single nave church with long presbytery, build in 1502 in late gothic style. Later baroquised, with remodelled bell—gable (1668) and added entrance shed. Above entrance inscription MyCCCCCy = 1502 (Y is not "V" (five), but two "1" = II = 2) Complex surrounded with wall and porton (with year 18M28) Special features: Black limestone (glaževec; friable, not lasting); On west portal stonemasons' signs; signature of Anže Rojina (M.A.R. = magister Anže Rojina); crosses on the plaster Platy limestone in elements state of conservation: Notes: Descriptor: Neža Čebron Lipovec, Mitja Guštin, Božo Premrl Date of fieldwork: 4.6.2013 GEOLOGY limestone elements: 0 walls 1 main roof 2 extension roof 2a roof of carport 2b little extension roof 2c externial entrence 3 stone bordure 4 corbels 5 corner stones 6 window frame 6a window frame 6a window frame 7 doorpost: 7a doorpost of carport | RoR description number | SLOVENSKI KRAS / SLOVENIAN KARST 4 | | |
|--|-------------------------------|--|--|--|
| Name (official and common): Address (location): Cadastral number. Community: Coordinates: Owner / contact: Heritage status / protection: Typology: Short description (ground plan, architectural elements, chronology): Special features: Special features: Back limestone in elements / state of conservation: Notes: Descriptor: Date of fieldwork: Descriptor: Date of fieldwork: Cerkev Marijinega vnebovzetja / Church of the Assumption of Mary Smarje pri Sežani (6007/2, c.c. Sežana 6007/2, c.c. Sežana Special Skapin from Sežana Special skapin from Sežana Special local monument); EŠD: 746 church The single nave Karstic church The single nave Karstic church The single nave church with long presbytery, build in 1502 in late gothic style. Later baroquised, with remodelled bell—gable (1668) and added entrance shed. Above entrance inscription M1CCCCC1Y = 1502 (Y is not "V" (five), but two "I" = II = 2) Complex surrounded with wall and porton (with year 18M28) Black limestone (glaževec; friable, not lasting); On west portal stonemasons' signs; signature of Anže Rojina (M.A.R. = magister Anže Rojina); crosses on the plaster Platy limestone in elements / state of conservation: Notes: Descriptor: Neža Čebron Lipovec, Mitja Guštin, Božo Premrl 4.6.2013 GEOLOGY limestone elements: 0 walls 1 main roof 2 extension roof 2a roof of carport 2b little extension roof 2c externial entrence 3 stone bordure 4 corbels 5 corner stones 6 window frame 6 a window frame 6 a window frame 6 a window frame 7 doorpost: 7 a doorpost of carport | CULTURAL HERITAGE | CHITHDAL HEDITACE | | |
| Cadastral community: Coordinates: Owner / contact: Heritage status / protection: RKC; contact: parish priest Sandi Škapin from Sežana spomenik lokalnega pomena (local monument); EŠD: 746 Use (original): Typology: Short description (ground plan, architectural elements, chronology): The single nave Karstic church The single nave church with long presbytery, build in 1502 in late gothic style. Later baroquised, with remodelled bell—gable (1668) and added entrance shed. Above entrance inscription M1CCCCCQY = 1502 (Y is not "V" (five), but two "I" = II = 2) Complex surrounded with wall and porton (with year 18M?8) Special features: Black limestone (glaževec; friable, not lasting); On west portal stonemasons' signs; signature of Anže Rojina (M.A.R. = magister Anže Rojina); crosses on the plaster Platy limestone in elements / state of conservation: Notes: Descriptor: Date of fieldwork: 4.6.2013 GEOLOGY limestone elements: 0 walls 1 main roof 2 extension roof 2 a roof of carport 2b little extension roof 2c externial entrence 3 stone bordure 4 corbels 5 corner stones 6 window frame 6 a window frame 7 doorpost: 7 a doorpost of carport | Name (official and common): | | | |
| Conmunity: Coordinates: Owner / contact: Heritage status / protection: Short description (ground plan, architectural elements, chronology): Special features: Black limestone in elements / State of conservation: Notes: Descriptor: Platy limestone in elements / State of conservation: Notes: Descriptor: Neža Čebron Lipovec, Mitja Guštin, Božo Premrl Date of fieldwork: 4.6.2013 Y= 412.165, X= 64.817 RKC; contact: parish priest Sandi Škapin from Sežana Heritage status / promese Sana Heritage apomena (local monument); EŠD: 746 Rugina (local monument); EŠD: 746 The single nave Karstic church The single nave Karstic church The single nave church with long presbytery, build in 1502 in late gothic style. Later baroquised, with remodelled bell—gable (1668) and added entrance shed. Above entrance inscription M ₁ CCCCC ₁ Y = 1502 (Y is not "V" (five), but two "I" = II = 2) Complex surrounded with wall and porton (with year 18M?8) Black limestone (glaževec; friable, not lasting); On west portal stonemasons' signs; signature of Anže Rojina (M.A.R. = magister Anže Rojina); crosses on the plaster Platy limestone in elements / Roof covered with skrle; stone floor in church All in good state of preservation. Notes: Descriptor: Neža Čebron Lipovec, Mitja Guštin, Božo Premrl 4.6.2013 GEOLOGY little extension roof 2 cordinates description for the plant of the plant | Address (location): | Šmarje pri Sežani | | |
| Y= 412.165, X= 64.817 RKC; contact: parish priest Sandi Škapin from Sežana spomenik lokalnega pomena (local monument); EŠD: 746 Use (original): church Typology: The single nave Karstic church The single nave church with long presbytery, build in (sground plan, architectural elements, chronology): The single nave church with long presbytery, build in 1502 in late gothic style. Later baroquised, with remodelled bell—gable (1668) and added entrance shed. Above entrance inscription MtCCCCty = 1502 (Y is not "V" (five), but two "I" = II = 2) Complex surrounded with wall and porton (with year 18M28) | Cadastral number, | | | |
| Owner / contact: RKC; contact: parish priest Sandi Škapin from Sežana spomenik lokalnega pomena (local monument); EŠD: 746 Use (original): church Typology: The single nave Karstic church Short description (ground plan, architectural elements, chronology): The single nave church with long presbytery, build in 1502 in late gothic style. Later baroquised, with remodelled bell—gable (1668) and added entrance shed. Above entrance inscription MtCCCCtty = 1502 (Y is not "V" (five), but two "I" = II = 2) Special features: Black limestone (glaževec; friable, not lasting); On west portal stonemasons' signs; signature of Anže Rojina (M.A.R. = magister Anže Rojina); crosses on the plaster Platy limestone in elements / state of conservation: Roof covered with skrle; stone floor in church All in good state of preservation. Notes: Neža Čebron Lipovec, Mitja Guštin, Božo Premrl Date of fieldwork: 4.6.2013 GEOLOGY O walls limestone elements: 0 walls 1 main roof 2 externsion roof 2 externsion roof 2 externial entrence 3 stone bordure 4 corbels 5 corner stones 6 window frame 6 doorpost: 7 doorpost of carport | community: | | | |
| Spomenik lokalnega pomena (local monument); EŠD: 746 | Coordinates: | Y= 412.165, X= 64.817 | | |
| Spomenik lokalnega pomena (local monument); EŠD: 746 | Owner / contact: | RKC; contact: parish priest Sandi Škapin from Sežana | | |
| Typology: Short description (ground plan, architectural elements, chronology): The single nave Karstic church The single nave church with long presbytery, build in 1502 in late gothic style. Later baroquised, with remodelled bell—gable (1668) and added entrance shed. Above entrance inscription MtCCCCCty = 1502 (Y is not "V" (five), but two "I" = II = 2) Complex surrounded with wall and porton (with year 18M?8) Special features: Black limestone (glaževec; friable, not lasting); On west portal stonemasons' signs; signature of Anže Rojina (M.A.R. = magister Anže Rojina); crosses on the plaster Platy limestone in elements / state of conservation: Notes: Descriptor: Neža Čebron Lipovec, Mitja Guštin, Božo Premrl Date of fieldwork: 4.6.2013 GEOLOGY limestone elements: 0 walls 1 main roof 2 extension roof 2a roof of carport 2b little extension roof 2c externial entrence 3 stone bordure 4 corbels 5 corner stones 6 window frame 6a window frame 6a window frame 6a window frame 7 doorpost: 7a doorpost of carport | Heritage status / protection: | spomenik lokalnega pomena (local monument); EŠD: | | |
| Typology: Short description (ground plan, architectural elements, chronology): The single nave Karstic church The single nave church with long presbytery, build in 1502 in late gothic style. Later baroquised, with remodelled bell—gable (1668) and added entrance shed. Above entrance inscription MtCCCCCtY = 1502 (Y is not "V" (five), but two "I" = II = 2) Complex surrounded with wall and porton (with year 18M?8) Special features: Black limestone (glaževec; friable, not lasting); On west portal stonemasons' signs; signature of Anže Rojina (M.A.R. = magister Anže Rojina); crosses on the plaster Platy limestone in elements / state of conservation: Notes: Descriptor: Neža Čebron Lipovec, Mitja Guštin, Božo Premrl Date of fieldwork: 4.6.2013 GEOLOGY limestone elements: 0 walls 1 main roof 2 extension roof 2a roof of carport 2b little extension roof 2c externial entrence 3 stone bordure 4 corbels 5 corner stones 6 window frame 6a window frame 6a window frame 6a window frame 7 doorpost: 7a doorpost of carport | Use (original): | church | | |
| 1502 in late gothic style. Later baroquised, with remodelled bell—gable (1668) and added entrance shed. Above entrance inscription M1CCCCC1Y = 1502 (Y is not "V" (five), but two "I" = II = 2) Complex surrounded with wall and porton (with year 18M?8) Special features: | Typology: | The single nave Karstic church | | |
| 1502 in late gothic style. Later baroquised, with remodelled bell—gable (1668) and added entrance shed. Above entrance inscription M1CCCCC1Y = 1502 (Y is not "V" (five), but two "I" = II = 2) Complex surrounded with wall and porton (with year 18M?8) Special features: | | | | |
| Above entrance inscription M\(CCCC\(\chi Y = 1502\) (Y is not "V" (five), but two "I" = II = 2) Complex surrounded with wall and porton (with year 18M?8) Special features: Black limestone (glaževec; friable, not lasting); On west portal stonemasons' signs; signature of Anže Rojina (M.A.R. = magister Anže Rojina); crosses on the plaster Platy limestone in elements / Roof covered with skrle; stone floor in church All in good state of preservation. Notes: Descriptor: Neža Čebron Lipovec, Mitja Guštin, Božo Premrl Date of fieldwork: 4.6.2013 GEOLOGY limestone elements: 0 walls 1 main roof 2 extension roof 2a roof of carport 2b little extension roof 2c externial entrence 3 stone bordure 4 corbels 5 corner stones 6 window frame 6a window frame 7 doorpost: 7a doorpost of carport | (ground plan, architectural | 1502 in late gothic style. Later baroquised, with | | |
| Above entrance inscription M\(CCCC\(\chi Y = 1502\) (Y is not "V" (five), but two "I" = II = 2) Complex surrounded with wall and porton (with year 18M?8) Special features: Black limestone (glaževec; friable, not lasting); On west portal stonemasons' signs; signature of Anže Rojina (M.A.R. = magister Anže Rojina); crosses on the plaster Platy limestone in elements / Roof covered with skrle; stone floor in church All in good state of preservation. Notes: Descriptor: Neža Čebron Lipovec, Mitja Guštin, Božo Premrl Date of fieldwork: 4.6.2013 GEOLOGY limestone elements: 0 walls 1 main roof 2 extension roof 2a roof of carport 2b little extension roof 2c externial entrence 3 stone bordure 4 corbels 5 corner stones 6 window frame 6a window frame 7 doorpost: 7a doorpost of carport | elements, chronology): | remodelled bell –gable (1668) and added entrance shed. | | |
| not "V" (five), but two "I" = II = 2) Complex surrounded with wall and porton (with year 18M?8) Special features: Black limestone (glaževec; friable, not lasting); On west portal stonemasons' signs; signature of Anže Rojina (M.A.R. = magister Anže Rojina); crosses on the plaster Platy limestone in elements / Roof covered with skrle; stone floor in church state of conservation: Notes: Descriptor: Neža Čebron Lipovec, Mitja Guštin, Božo Premrl Date of fieldwork: 4.6.2013 GEOLOGY limestone elements: 0 walls 1 main roof 2 extension roof 2a roof of carport 2b little extension roof 2c externial entrence 3 stone bordure 4 corbels 5 corner stones 6 window frame 6a window frame 6a window frame 7 doorpost: 7a doorpost of carport | | | | |
| Complex surrounded with wall and porton (with year 18M?8) Special features: Black limestone (glaževec; friable, not lasting); On west portal stonemasons' signs; signature of Anže Rojina (M.A.R. = magister Anže Rojina); crosses on the plaster Platy limestone in elements / Roof covered with skrle; stone floor in church All in good state of preservation. Notes: Descriptor: Neža Čebron Lipovec, Mitja Guštin, Božo Premrl Date of fieldwork: 4.6.2013 GEOLOGY limestone elements: 0 walls 1 main roof 2 extension roof 2a roof of carport 2b little extension roof 2c externial entrence 3 stone bordure 4 corbels 5 corner stones 6 window frame 6a window frame 6a window frame 7 doorpost: 7a doorpost of carport | | | | |
| On west portal stonemasons' signs; signature of Anže Rojina (M.A.R. = magister Anže Rojina); crosses on the plaster Platy limestone in elements / state of conservation: Notes: Descriptor: Neža Čebron Lipovec, Mitja Guštin, Božo Premrl Date of fieldwork: 4.6.2013 GEOLOGY limestone elements: 0 walls 1 main roof 2 extension roof 2a roof of carport 2b little extension roof 2c externial entrence 3 stone bordure 4 corbels 5 corner stones 6 window frame 6a window frame 6a window frame 7 doorpost: 7a doorpost of carport | | Complex surrounded with wall and porton (with year | | |
| Rojina (M.A.R. = magister Anže Rojina); crosses on the plaster Platy limestone in elements / Roof covered with skrle; stone floor in church All in good state of preservation. Notes: Descriptor: Neža Čebron Lipovec, Mitja Guštin, Božo Premrl Date of fieldwork: 4.6.2013 GEOLOGY limestone elements: 0 walls 1 main roof 2 extension roof 2a roof of carport 2b little extension roof 2c externial entrence 3 stone bordure 4 corbels 5 corner stones 6 window frame 6a window frame 6a window frame 7 doorpost: 7a doorpost of carport | Special features: | Black limestone (glaževec; friable, not lasting); | | |
| plaster Platy limestone in elements / Roof covered with skrle; stone floor in church All in good state of preservation. Notes: Descriptor: Neža Čebron Lipovec, Mitja Guštin, Božo Premrl Date of fieldwork: 4.6.2013 GEOLOGY limestone elements: 0 walls 1 main roof 2 extension roof 2a roof of carport 2b little extension roof 2c externial entrence 3 stone bordure 4 corbels 5 corner stones 6 window frame 6a window frame 6a window frame 7 doorpost: 7a doorpost of carport | | On west portal stonemasons' signs; signature of Anže | | |
| All in good state of preservation. Notes: Descriptor: Neža Čebron Lipovec, Mitja Guštin, Božo Premrl Al6.2013 GEOLOGY limestone elements: 0 walls 1 main roof 2 extension roof 2a roof of carport 2b little extension roof 2c externial entrence 3 stone bordure 4 corbels 5 corner stones 6 window frame 6a window frame 7 doorpost: 7a doorpost of carport | | | | |
| Notes: Descriptor: Neža Čebron Lipovec, Mitja Guštin, Božo Premrl 4.6.2013 GEOLOGY limestone elements: 0 walls 1 main roof 2 extension roof 2a roof of carport 2b little extension roof 2c externial entrence 3 stone bordure 4 corbels 5 corner stones 6 window frame 6a window frame 7 doorpost: 7a doorpost of carport | Platy limestone in elements / | Roof covered with skrle; stone floor in church | | |
| Descriptor: Date of fieldwork: 4.6.2013 GEOLOGY limestone elements: 0 walls 1 main roof 2 extension roof 2a roof of carport 2b little extension roof 2c externial entrence 3 stone bordure 4 corbels 5 corner stones 6 window frame 6a window frame 7 doorpost: 7a doorpost of carport | state of conservation: | All in good state of preservation. | | |
| Date of fieldwork: 4.6.2013 GEOLOGY limestone elements: 0 walls 1 main roof 2 extension roof 2a roof of carport 2b little extension roof 2c externial entrence 3 stone bordure 4 corbels 5 corner stones 6 window frame 6a window frame 7 doorpost: 7a doorpost of carport | Notes: | - | | |
| GEOLOGY limestone elements: 0 walls 1 main roof 2 extension roof 2a roof of carport 2b little extension roof 2c externial entrence 3 stone bordure 4 corbels 5 corner stones 6 window frame 6a window frame 7 doorpost: 7a doorpost of carport | Descriptor: | Neža Čebron Lipovec, Mitja Guštin, Božo Premrl | | |
| limestone elements: 0 walls 1 main roof 2 extension roof 2a roof of carport 2b little extension roof 2c externial entrence 3 stone bordure 4 corbels 5 corner stones 6 window frame 6a window frame 7 doorpost: 7a doorpost of carport | Date of fieldwork: | 4.6.2013 | | |
| 1 main roof 2 extension roof 2a roof of carport 2b little extension roof 2c externial entrence 3 stone bordure 4 corbels 5 corner stones 6 window frame 6a window frame 7 doorpost: 7a doorpost of carport | GEOLOGY | | | |
| 2 extension roof 2a roof of carport 2b little extension roof 2c externial entrence 3 stone bordure 4 corbels 5 corner stones 6 window frame 6a window frame 7 doorpost: 7a doorpost of carport | limestone elements: | 0 walls | | |
| 2a roof of carport 2b little extension roof 2c externial entrence 3 stone bordure 4 corbels 5 corner stones 6 window frame 6a window frame 7 doorpost: 7a doorpost of carport | | 1 main roof | | |
| 2b little extension roof 2c externial entrence 3 stone bordure 4 corbels 5 corner stones 6 window frame 6a window frame 7 doorpost: 7a doorpost of carport | | 2 extension roof | | |
| 2c externial entrence 3 stone bordure 4 corbels 5 corner stones 6 window frame 6a window frame 7 doorpost: 7a doorpost of carport | | 2a roof of carport | | |
| 3 stone bordure 4 corbels 5 corner stones 6 window frame 6a window frame 7 doorpost: 7a doorpost of carport | | 2b little extension roof | | |
| 4 corbels 5 corner stones 6 window frame 6a window frame 7 doorpost: 7a doorpost of carport | | 2c externial entrence | | |
| 5 corner stones 6 window frame 6a window frame 7 doorpost: 7a doorpost of carport | | 3 stone bordure | | |
| 6 window frame 6a window frame 7 doorpost: 7a doorpost of carport | | 4 corbels | | |
| 6a window frame 7 doorpost: 7a doorpost of carport | | 5 corner stones | | |
| 7 doorpost: 7a doorpost of carport | | 6 window frame | | |
| 7a doorpost of carport | | 6a window frame | | |
| 7a doorpost of carport | | 7 doorpost: | | |
| | | <u> </u> | | |
| is done post of career from critical control | | 7b doorpost of externial entrence | | |

| | 7. · 44 · |
|------------------------------|------------------------|
| | 7c jutting roof |
| | 8 bell tower |
| | 9 corbels of carport |
| | 10 final stone |
| | 11pilars |
| | 12voult of balcony |
| | 13 balustrade |
| | 14 holy water font |
| | 14 a holy water font |
| | 15 stone for donations |
| | 16 stairs |
| | 17 vault |
| | 18 altar |
| | 18 a altar 1 |
| | 18 b altar 2 |
| | 19 bordure |
| | 20 stone floor |
| Quarries/excavation sites in | av brone novi |
| neighbourhood: | |
| Notes: | |
| | |
| Descriptor: | |
| Datum: | |


Illustrative enclosure to the Roof of Rock description Sheet:

Topographic map, general:



Geopedia.si

Topographic map, local:



TK 25 (http://rkg.gov.si/GERK/viewer)

Ortophoto / satellite photo:




Ortophoto cyclic recording 2012-2014 (http://gis.arso.gov.si/atlasokolja)

Modern cadastral map:



6007/2, c. c. Sežana

Historical maps:




Franciscan cadastral map 1870 (http://www.catasti.archiviodistatotrieste.it/)

Historical photography:



Situation 1969 (photo: Slovenski etnografski muzej)





Situation ca. 1970 (photo: ZVKDS)

Photo documentation:



































Fieldwork, 4.6.2013 (photo M.Guštin)


Architectural drawings:























Authors: Mitja Skubin, Katja Kosič, junij 2014

8. Cerkev Marijinega vnebovzetja na Guri, Plešivica pri Povirju, Slovenia

| RoR description number | SLOVENSKI KRAS / SLOVENIAN KARST 5 |
|-------------------------------|--|
| CULTURAL HERITAGE | |
| Name (official and common): | Cerkev Marijinega vnebovzetja na Guri / Church of the Assumption of Mary |
| Address (location): | Plešivica pri Sežani ("Gura pri Povirju") |
| Cadastral number, | 92, c.c. Povir |
| community: | |
| Coordinates: | Y= 416.136, X= 62.125 |
| Owner / contact: | RKC; contact: parish priest Sandi Škapin from Sežana, also Franc Škrinjar from Povir |
| Heritage status / protection: | spomenik lokalnega pomena (local monument); EŠD: 7338 |
| Use (original): | subsidiary, pilgrimage church |
| Typology: | The single nave church with a western bell tower |
| Short description | Built in 16 th c. First renovation with building of new |
| (ground plan, architectural | presbytery and entrance shed between 1642-1647. |
| elements, chronology): | Baroque modernisation at the end of 17 th and in 18 th c. |
| | Bell tower from 1836. |
| Special features: | Preserved original volume and construction, preserved |
| | historic arrangement of architecture. |
| | Only church on Carst, covered entirely by skrle. |
| Platy limestone in elements / | All roofs covered with plate limestone skrle. |
| state of conservation: | Western part of building rotten by leaking that |
| | destroying wooden roof construction. Skrle of minor |
| | quality stored nearby. |
| Notes: | |
| Descriptor: | Neža Čebron Lipovec, Božo Premrl |
| Date of fieldwork: | 4.10.2013 |
| GEOLOGY | |
| limestone elements: | 0 walls |
| unicatoric coments. | 0a rock |
| | 1 main roof |
| | 2 extension roof |
| | 3 stone bordure |
| | 4 corbels for gully |
| | 4a gully |
| | 5 corner stones |
| | 6 window frame |
| | 7 doorpost: |
| | 8 bell tower |
| | 8a vault of bell tower |
| | 8 stairs: |
| | 9 outside pavement |
| | 9a inside pavement |


| | 10 final stone 11 altar 12 pillars 13 stairs 14 stone pavement |
|---|--|
| Quarries/excavation sites in neighbourhood: | |
| Notes: | |
| Descriptor: | |
| Datum: | |

Illustrative enclosure to the Roof of Rock description Sheet:

Topographic map, general:



Topographic map, local:



Ortophoto / satellite photo:




Ortophoto cyclic recording 2012-2014 (http://gis.arso.gov.si/atlasokolja)

Modern cadastral map:



92, c.c. Povir (http://rkg.gov.si/GERK/viewer.jsp)

Historical maps:



Franciscan cadastral map (situla.org)

Photo documentation:

























Fieldwork, 4.6.2013 (photo N. Čebron Lipovec, Premrl)


Architectural drawings:























Author: Katja Kosić, uia

9. Domačija »Pri Blaževih«, Gorenje pri Divači, Slovenia

| RoR description number | SLOVENSKI KRAS / SLOVENIAN KARST 1 |
|--|--|
| | |
| CULTURAL HERITAGE | II D'DI V'I |
| Name (official and common): | Home »Pri Blaževih« |
| Address (location): | Gorenje pri Divači 14 |
| Cadastral number, | 121/1, c.c. Povir |
| community: | W 41051A W (140A |
| Coordinates: | Y=418512, X=61492 |
| Owner / contact: | Owner: Mirko Grželj; phone 041 225 283 |
| Heritage status / protection: | spomenik lokalnega pomena (local monument); ESD: 7338 |
| Use (original): | Till 1956 dwelling house, later outhouse. |
| Typology: | One flor farm house with "spahnjenca" |
| Short description | Typical karstic home with walled farmyard ("borjač"). |
| (ground plan, architectural | House has two drips, added kitchen (spahnjenca) with |
| elements, chronology): | four-sixth groud plan and oven with triangular drip. |
| | Home is visible already on Franciscan cadastral map from 1818, while some other buildings in village have cut in dates from beginning of 18 th century. |
| Special features: | Preserved original volume and construction, preserved historic arrangement of rooms, <i>Spahnjenca</i> with bread oven. |
| Platy limestone in elements / state of conservation: | Roofs of main part, spahnjenca and oven are covered with <i>skrle</i> . Jutting roof over entrance, pavement (inside »škrle«; outside »šeliž«), shelf around chimney, terrace around water cistern. All in good state of preservation. |
| Notes: | |
| Descriptor: | Neža Čebron Lipovec, Mitja Guštin, Božo Premrl |
| Date of fieldwork: | 4.6.2013 |
| GEOLOGY | |
| limestone elements: | 0 walls: |
| | 1 main roof: |
| | 2 extension roof: |
| | 3 oven roof: |
| | 4 corbels for gullys: |
| | 4a gully |
| | 5 corner stones: |
| | 6 window frame |
| | 7 doorpost: |
| | 7a door jutting roof: |
| | 8 stairs: |
| | 9 outside pavement: |

| | 9a inside pavement: 10 yard wall: 11 scarp of cistern: 12 rim of cistern: 13 trough 1897: 14 stone vessel: |
|---|---|
| | 15 stone vessel: |
| Quarries/excavation sites in neighbourhood: | <u>Gabričje</u> – once excavation site, two or three years ago trial digs by Perčič. <u>Pri Rebčevih</u> (Jakob in Ivan Rebec, stonemasons with own query on their land) – Gorenje 8. |
| Notes: | |
| Descriptor: | |
| Datum: | |
| | |

 ${\it Illustrative\ enclosure\ to\ the\ Roof\ of\ Rock\ description\ Sheet:}$

Topographic map, general:



Geopedia.si

Topographic map, local:



Ortophoto / satellite photo:



Modern cadastral map:



121/1, c.c. Povir

Historical maps:



Franciscan cadastral map (1818)

Historical photography:






Photodocumentation:













Fieldwork, 4.6.2013 (photo M.Guštin)

Architectural drawings: 1 6a-e \square

Author: Anja Premk

10. Domačija »Škrateljnovi«, Divača, Slovenia


| RoR description number | SLOVENSKI KRAS / SLOVENIAN KARST 1 | | |
|--|---|--|--|
| CULTURAL HERITAGE | | | |
| Name (official and common): | Home »Škrateljnova« | | |
| Address (location): | Divača, Kraška cesta 26 | | |
| Cadastral number, | 669/4, 670/3, c.c. Divača | | |
| community: | 0071, 01010, 0100 211 1101 | | |
| Coordinates: | GKY= 420.219; GKX= 60.494 | | |
| Owner / contact: | Owner: Muzej slovenskih filmskih igralcev | | |
| Heritage status / protection: | spomenik lokalnega pomena (local monument); EŠD: 94 | | |
| Use (original): | Till 1956 dwelling house | | |
| Typology: | One flor farm house | | |
| Short description | Typical karstic farmer homestead of "closed" | | |
| (ground plan, architectural | architectural concept of 17 th c. Consisted of double (?) | | |
| elements, chronology): | spahnjenca, stable (modernized), barn (modernized), cistern, new drystone support wall. | | |
| | Home is visible already on Franciscan cadastral map | | |
| | from 1818, while some other buildings in village have | | |
| | cut in dates from beginning of 18 th century. | | |
| Special features: | Preserved original volume and construction, preserved | | |
| | historic arrangement of rooms. | | |
| | Visible capillary moisture in spahnjenca, no drainage, | | |
| | lime plaster with lacunas for paintings on the front | | |
| | façade; | | |
| | Authors of renovation: Vojteh Ravnikar; Ernest | | |
| Distriction and are also also and a | Milčinovič, Matjaž Bolčina, Teja Savelli | | |
| Platy limestone in elements / state of conservation: | Roofs of main part and oven are covered with <i>skrle</i> . All in good state of preservation. | | |
| sidile of conservation. | An in good state of preservation. | | |
| Notes: | , | | |
| Descriptor: | Neža Čebron Lipovec, Mitja Guštin, Božo Premrl | | |
| Date of fieldwork: | 4.6.2013 | | |
| GEOLOGY | | | |
| limestone elements: | 0 walls: | | |
| | 1 main roof: | | |
| | 1a main roof: | | |
| | 1b main roof: | | |
| | 2 extension roof | | |
| | 3 oven roof: | | |
| | 4 extension roof 4a extension roof | | |
| | 4b little extension roof | | |
| | 6 window frame | | |
| | 7 doorpost | | |
| | 8 built inscription stone | | |
| | _ | | |

| | 9 outside pavement: |
|------------------------------|--|
| | 9a inside pavement: |
| | 10 pilar of balcony |
| | 10a stone shelf |
| | 10b final pilar of fence |
| | 11 stone paviment |
| | 12 rim of cistern |
| | 13 base of monument |
| Quarries/excavation sites in | Gabričje – once excavation site, two or three years ago |
| neighbourhood: | trial digs by Perčič. Pri Rebčevih (Jakob in Ivan Rebec, |
| | stonemasons with own query on their land) – Gorenje 8. |
| Notes: | |
| Descriptor: | |
| Datum: | |
| | |

Illustrative enclosure to the Roof of Rock description Sheet:

Topographic map, general:





Ortophoto / satellite photo:




Ortophoto cyclic recording 2012-2014 (http://gis.arso.gov.si/atlasokolja)

Modern cadastral map:



669/4, 670/3, c.c. Divača (http://rkg.gov.si/GERK)

Historical maps:



Franciscan cadastral map (situla.org)

Historical photography:



Situation in the middle of 20th c. (source: Muzej slovenskih igralcev, Divača)



Situation before renovation, (source: Muzej slovenskih igralcev, Divača)









Situation in 1969, (source: Slovenski etnografski muzej, Ljubljana)

Photo documentation:















Fieldwork, 4.6.2013 (photo M.Guštin)

Architectural drawings:





ORIS PRITLIČIA 1 2 3 4 5m




Authors: <u>Matjaž Bolčina</u>, <u>Ernest Milčinovič</u>, <u>Teja Savelli</u>


11. Crkva sv. Nikole, Nin, Croatia

| RoR description number | ZADARSKA ŽUPANIJA / ZADAR COUNTY |
|-------------------------------|---|
| | |
| CULTURAL HERITAGE | |
| Name (official and common): | Crkva Sv. Nikole, Nin (Church of St. Nicholas, Nin) |
| Address (location): | Prahulje, near the town Nin, Zadar County |
| Cadastral number, | 3277/8, Zaton-Nin, Nin |
| community: | |
| Coordinates: | φ = 44°13'51" N λ=15°10'42" E |
| Owner / contact: | Župni ured Sv. Anselma, Branimirova 2, 23232 Nin, tel/faks: 023/264-162. |
| Heritage status / protection: | zaštićeno kulturno dobro (protected cultural heritage); Z-1336 |
| Use (original): | Sacral building, occasionally in use. |
| Typology: | Central early-Romanesque church with irregular circular ground plan. |
| Short description | The church was built on a prehistoric tumulus in a field |
| (ground plan, architectural | between Nina and Zaton (Prahulje). It has a trefoil |
| elements, chronology): | ground plan with vaulted conch. The center of the building is vaulted with a dome (cross-ribbed vault). It is early Romanesque building from the 12th century. |
| Special features: | The walls of the buildings were built with roughly shaped limestone and originally were covered with plaster. During the 17th century, in the Turkish wars, church became a military observation post and over the dome was added the battlement/crenelation. |
| Platy limestone in elements / | All vaults are covered with a platy limestone, as well as |
| state of conservation: | a cornice. All in good state of preservation. |
| Notes: | |
| Descriptor: | Silvije Pranjić |
| Date of fieldwork: | 18.IX.2013. |
| GEOLOGY | |

| Selected limestone elements: | 0 walls: 1 main dome: 2 extension roof: 3 battlement/crenelation 3a merlons 3b crenels 4 cross-ribbed vault 5a original romanesque corbels/console 5b new corbels-restoration at the end of the 20th century 6 cornice 7 door frame: 8 pilaster: 9 transom -restoration at the end of the 20th century 10 door corbels |
|---|--|
| Quarries/excavation sites in neighbourhood: Notes: | 11 doorpost |
| Descriptor: Datum: | |

Illustrative enclosure to the Roof of Rock description Sheet:







 $Or tophoto / satellite\ photo(ARKOD):$



 $Modern\ cadastral\ map(ARKOD)$:



Photodocumentation:



Figure 1



Figure 2



Figure 3



Figure 4




Figure 5




Figure 6




Figure 7



Figure 8

Fieldwork, 18.IX.2013. (photo S. Pranjić)

Architectural drawings:



(Petricioli, 2002)


12. Crkva sv. Ivana krstitelja, Medviđa, Benkovac, Croatia

| RoR description number | ZADARSKA ŽUPANIJA / ZADAR COUNTY |
|--|---|
| CULTURAL HERITAGE | |
| Name (official and common): | Crkva Sv. Ivana Krstitelja (Church Of St.John The Baptist) |
| Address (location): | local graveyard, Medviđa, Zadar County |
| Cadastral number, | 1/1 i 1/3, Medviđa |
| community: | |
| Coordinates: | φ= 44°06'08" N λ=15°46'46" E |
| Owner / contact: | Župni ured Medviđa, 23450 Obrovac |
| Heritage status / protection: | preventivno zaštićeno kulturno dobro |
| | (a preventive protected cultural heritage) |
| Use (original): | Sacral building, occasionally in use. |
| Typology: | Late medieval rural building with "Bukovica type" roof. |
| Short description | Church of St. John the Baptist is a cemetery church in |
| (ground plan, architectural elements, chronology): | village Medviða. It was built in the 13th or 14th century. The building is very picturesque because of its location at |
| ciemenis, enronotogy). | the foot of the rock, which rises above the tall tower in |
| | front of the church. The church has an elongated |
| | rectangular floor plan with a rectangular apse prominent in |
| | the area on the eastern side. It was built of stone plastered |
| | on the outside. There is no portal in the front because it is |
| | close to the stone cliff. The roof construction of the nave is |
| | a wooden, a vaulted apse is slightly broken vault. |
| Special features: | St. John the Baptist in Medviđa is a remarkable architectural |
| | monument, unique in Zadar County because of the position, |
| | shape, preserved roof cover, high tower and dual confessional use. |
| Platy limestone in elements / | Gabled roof is covered with large rough-cut stone |
| state of conservation: | slabs(Bukovica typ). The roof was recently restored. |
| , | 51, |
| Notes: | GI P(|
| Descriptor: | Silvije Pranjić |
| Date of fieldwork: | 24.VI. 2013. |
| GEOLOGY | |
| Selected limestone elements: | 0 walls |
| | 1 main roof (nave ceiling) |
| | 2 extension roof (vaulted sanctuary) |
| | 3 bell tower |
| | 4a old wooden roof constructions |
| | 4b new wooden roof construction |
| | 5 vaulted sanctuary/apse 6 altar |
| Quarries/excavation sites in | O artar |
| neighbourhood: | |
| | |


| Notes: | |
|-------------|--|
| Descriptor: | |
| Datum: | |
| | |

Illustrative enclosure to the Roof of Rock description Sheet:

Topographic map, general (ARKOD):



Topographic map, local (ARKOD):







Modern cadastral map (ARKOD):



Photodocumentation:



Figure 9



Figure 10



Figure 11




Figure 12



Figure 13




Figure 14



Figure 15




Figure 16Fieldwork, 24.VI. 2013. (photo S. Pranjić)


13. Stone sidewalks in Zadar old town, Croatia

| RoR description number | ZADARSKA ŽUPANIJA / ZADAR COUNTY |
|--|---|
| OVER THE AVER THE AVE | |
| CULTURAL HERITAGE | |
| Name (official and common): | stone sidewalks in Zadar old town |
| Address (location): | Zadar, Zadar County |
| Cadastral number, | 10777; 10769; 9934; 9854; 10772 |
| community: | |
| Coordinates: | φ = 44°06'51" N λ = 15°13'40" E |
| Owner / contact: | City of Zadar |
| Heritage status / protection: | non protected |
| Use (original): | public foot traffic |
| Typology: | public sidewalks and pavaments |
| Short description | Throughout history, streets and squares of Zadar were |
| (ground plan, architectural | covered with stone slabs for several times. Since ancient |
| elements, chronology): | Roman times, the Middle Ages until today. But most of the |
| | the pavement today is from the time of Austro-Hungarian |
| | administration(late 19th century). They used the stone from |
| | the island Lavdara. This reddish limestone was chosen |
| | because of strength and resistance to foot traffic. Stone |
| | slabs were 5 to 15 cm thick. |
| Special features: | Originally plates were laid out in dry layer of red clayish |
| | soil. Today 2-3 cm thin plates are laid in concrete. |
| Platy limestone in elements / | Conditionally speaking this is platy limestone, roughly |
| state of conservation: | processed in square blocks. |
| | Unfortunately, in recent years these sidewalks are replaced |
| | with thin plates of white stone from Brač or Istria. |
| Notes: | |
| Descriptor: | Silvije Pranjić |
| | 0.1111.0010 |
| Date of fieldwork: | 9.VIII.2013. |
| GROV OGV | |
| GEOLOGY | |
| Selected limestone elements: | |
| Quarries/excavation sites in | |
| neighbourhood: | |
| Notes: | |
| Descriptor: | |
| Datum: | |
| | |

Illustrative enclosure to the Roof of Rock description Sheet:

Topographic map, general (ARKOD):





Ortophoto / satellite photo (ARKOD):







Photodocumentation:



Figure 17




Figure 18



Figure 3



Figure 4

Fieldwork, 9.VIII.2013. (photo S. Pranjić)


14. Crkva sv. Pelegrina, Savar, Dugi otok, Croatia

| RoR description number | ZADARSKA ŽUPANIJA / ZADAR COUNTY |
|--|--|
| CULTURAL HERITAGE | |
| Name (official and common): | Crkva sv. Pelegrina, Savar (Church of St. Peregrine, Savar) |
| Address (location): | Savar, Dugi otok, Zadarska županija |
| Cadastral number, community: | 20; 745, Savar |
| Coordinates: | φ= 44°03'46" N λ=15°01'25" E |
| Owner / contact: | Župni ured Gospe od Karmela, Savar, 23285 Brbinj. |
| Heritage status / protection: | protected cultural heritage (zaštićeno kulturno dobro) Z-1568 |
| Use (original): | sacral |
| Typology: | Pre-Romanesque church of the central type from IX. century. |
| Short description (ground plan, architectural elements, chronology): | Church is built on a small island connected to the mound on the Island of Dugi otok. This is the most valuable early medieval monument in archipelago of Zadar. The church consists of nave and sanctuary. Once there was a small sacristy to the sanctuary, but was demolished in 1958. year. Square sanctuary (2 x 3.35) is domed, and represents the core of the church. It was actually the original, a small Romanesque church, to which were later attached to a nave and sacristy. The church is extended in the 15th century when it was built on a rectangular vessel (6.7 x 5.8 m). In 1747. smallish bell tower was raised above the entrance to the church and sacristy added. |
| Special features: | According to tradition, the church was built by stonemasons of nearby quarry. This quarry is moust famous medieval quarry of Zadar. |
| Platy limestone in elements / state of conservation: | The dome of the first church (sacristy now) is covered with stone slabs. |


| | All in good state of preservation. |
|---|--|
| Notes: | |
| Descriptor: | Silvije Pranjić |
| Date of fieldwork: | 16. VII. 2013. |
| GEOLOGY | |
| Selected limestone elements: | 0 walls 1 stone roof (vaulted sanctuary) 2 main tile roof (nave ceiling) 3 bell tower 4 vaulted sanctuary/dome |
| Quarries/excavation sites in neighbourhood: | |
| Notes: | |
| Descriptor: | |
| Datum: | |
| | |

Illustrative enclosure to the Roof of Rock description Sheet:

Topographic map, general (ARKOD):




Topographic map, local (ARKOD):



Ortophoto / satellite photo (ARKOD):



Cadastral map (ARKOD):



Historical photography:





(I.Petricioli, 1954.)

Photodocumentation:



Figure 19



Figure 20




Figure 21



Figure 22

Architectural drawings:



(I.Petricioli, 1954.)

Fieldwork, 24.VI. 2013. (S. Pranjić)


15. Home "Čerina dvori", Podgrađe (near Benkovac), Croatia

| RoR description number | ZADARSKA ŽUPANIJA / ZADAR COUNTY |
|--|---|
| CULTURAL HERITAGE | |
| Name (official and common): | Home "Čerina dvori" |
| Address (location): | Podgrađe (near Benkovac), Zadar County |
| Cadastral number, | 801/1; 801/2; 835/2; 40/1; 40/2; 40/3; 40/5; |
| community: | Podgrađe, Lisišić, Benkovac |
| Coordinates: | ϕ = 44°01'05" N λ =15°40'06" E |
| Owner / contact: | Čerina Mile 023-687-011 |
| Heritage status / protection: | non protected |
| Use (original): | private houses |
| Typology: | complex of traditional stone houses-"dvori"; bukovica- |
| | type |
| Short description | The complex of family houses represents a typical example |
| (ground plan, architectural | of traditional architecture Dalmatian Zagora, type |
| elements, chronology): | bukovica. The complex of house grouped around a central |
| | walled courtyard, and consists of three residential houses, |
| | Vatrenica and two barns for livestock. Front yard, on a |
| | raised area is paved threshing floor. All the houses were |
| | built in extruded or roughly shaped stone. Are covered with stone plate thickness of 1 to 5 cm. The corners of buildings, |
| | window frames and doors were built of regularly chiseled |
| | block of stone. |
| Special features: | The walls of the buildings are minimally perforated. The |
| | modest decoration, except for window frames, makes a |
| | series of niche-hole in the upper triangular zone. They |
| | represent an ornament and a pigeon loft. On the roof of |
| | "crna kužina"/"vatrenica" is visible primitive chimney, a |
| | ventilation shaft called "badža". North the highest houses |
| | with an inner courtyard is associated with massive the stone |
| Platy limestone in elements / | stairs. All buildings have the roof of the plety limestone. Most of |
| Platy limestone in elements / state of conservation: | All buildings have the roof of the platy limestone. Most of the wall surfaces are also built stone plates. Courtyard and |
| state of conservation. | threshing front yard- "gumno" are also tiled. In |
| | perforations, plate stones were made niches, benches, holes |
| | for pigeons and chimney-opening. Houses were deserted |
| | even though, in good condition, while the roof |
| | "vatrenica"/"crna kužina" is jeopardized by collapsing. |
| | Unfortunately, none of the stone house in Podgrađe is |
| | under protection. |
| Notes: | G.1 b |
| Descriptor: | Silvije Pranjić |
| Date of fieldwork: | 17. V. 2014 |
| GEOLOGY. | |
| GEOLOGY | |

| Selected limestone elements: | 0 walls: 1 roofs: 2 courtyard pavement 3 corner stones: 4 window frames: 5 "klupica" bench 6 "golubinjaci"-niches in the wall for the pigeons 7 "gumno"- threshing front yard 8 courtyard wall: 9 rustic wooden roof construction 10 "badža"-rustic chimney |
|--|---|
| Quarries/excavation sites in neighbourhood: Notes: Descriptor: Datum: | |
| <i>В</i> шшп. | |

 ${\it Illustrative\ enclosure\ to\ the\ Roof\ of\ Rock\ description\ Sheet:}$

Topographic map, general:



Topographic map, local:



Ortophoto / satellite photo:



Modern cadastral map:



121/1, c.c. Podgrađe

Photodokumentation:



Figure 23



Figure 24



Figure 25



Figure 26







Figure 28



Figure 29



Figure 30



Figure 9



Figure 10

Fieldwork, 17. V. 2014 (photo S. Pranjić)

16. Trogir (katedrala), Croatia


| RoR description number | 3300 |
|--|--|
| CULTURAL HERITAGE | |
| Name (official and common): | Trogir, Triple apse of the Cathedral of St Lawrence |
| Address (location): | 11 ogis, 11 pre upse of the Guineurur of St Zumrence |
| Cadastral number, | 3798, 3799, 3800, 3801, 3802 K.O. Trogir |
| community: | , , , , |
| Coordinates: | E=479904 , N=4819708 |
| Owner / contact: | Owner: Župni ured sv. Lovre Trogir |
| Heritage status / protection: | Cathedral of St. Lawrence in Trogir / listed as a national built heritage and also as a part of the |
| | UNESCO World Heritage Site (Historic City of Trogir) / Z-3489 |
| Use (original): | Sacral monument-original use |
| Typology: Short description | Construction of the Cathedral of St Lawrence, built on the site of an earlier basilica and dominating the main square, began around 1200 and was added in the late 16th century. This relatively protracted period of construction has meant that successive architectural styles - Romanesque, Gothic and Renaissance - are all represented. The gothic 47 m-high bell tower has three sections in different styles, testimonial of the four centuries required for its completion, and a pyramidal roof. Cathedral of St. Lawrence in Trogir is a triple-naved |
| (ground plan, architectural elements, chronology): | basilica, each of the naves terminating in an apse. Inside the porch at the west end is the baptistery, which was built by Andrija Alesi with help from Niccolo di Giovanni of Florence. The baptistery is a characteristic example of the synthesis of late Gothic and early Renaissance stylistic features. Immediatly after the baptistery was completed, a contract was signed to erect to new chapel to the Blessed John of Ursini, a masterpiece of 15th century stone art and architecture. A bell tower started in the second half of the 13th century rises over the forcourt of the cathedral. The first section of the belfry is a Gothic work of masters Stjepan and Matej, the second a Venetian-gothic and the top floor and roof were built by Trifun Bokanic, with statues by Venetian sculptor Alessandro Vittoria. Triple apse, located on the east side of the Cathedral, is covered with platy limestone unlike the rest of the Cathedral roofs. |
| Special features: | |
| Platy limestone in elements / | Platy limestone is used on roof surfaces and eaves. |

| state of conservation: | |
|------------------------------|----------------------|
| Notes: | Protected by UNESCO. |
| Descriptor: | Ivo Vojnović |
| Date of fieldwork: | 3.10.2014 |
| | |
| | |
| | |
| GEOLOGY | |
| Selected limestone elements: | 1 walls |
| | 2 main roof |
| | 5 eaves |
| | 47 cornice eaves |
| Quarries/excavation sites in | |
| neighbourhood: | |
| Notes: | |
| Descriptor: | |
| Date: | |
| | |




Illustrative enclosure to the Roof of Rock description Sheet:


Topographic map, general



Croatian basic map (HOK):



Ortophoto:



Modern cadastral map:




Historical map Second Military Mapping Survey of Austrian Empire ca. 1830 (revision 1880) 1:2880 obtained from: State Archive – Split



Photodocumentation:







- Katedrala sv. Lovre u Trogiru, tlocrt; 1 osnovno tijelo bazilike oko 1210. do 1240. godine
- 2 dogradnje i pregradnja zapadnog portala od XIII. do kraja XIV. ili početka XV. stoljeća
- 3 kameni crkveni namještaj, ciborij i propovjedaonica oko 1260 1270 godine
- 4 predvorje XIV. stoljeće
- 5 kapela sv. Jeronima, krstionica, kapela sv. Ivana Tro-girskog, sakristija XV. stoljeće (sjeverozapadni prostori uz sakristiju XX. stoljeće)

- La cattedrale di S. Lorenzo a Traù (Trogir), pianta; 1 il corpo fondamentale della basilica intorno al 1210 fino al 1240,
- 2 aggiunte e modifiche al portale occidentale dal XIII alla fine del XIV o ai primi del XV sec.,
- 3 gli arredi sacri in pietra, il ciborio e il pulpito degli anni intorno al 1260–1270,
- 4 l'atrio del XIV secolo,
- 5 la cappella di S. Geronimo, il battistero, la cappella di S. Giovanni da Traù, la sacrestia del XV secolo (ambienti nordoccidentali accanto alla sacrestia del XX secolo).

17. Grohote village (Šolta). Ruića dvori, Croatia


| RoR description number | |
|--|---|
| CHI THDAL HEDITACE | |
| Name (official and common): | o. Šolta, Grohote, Ruića dvori |
| Address (location): | Ruića dvori 9 |
| Cadastral number, | 1313 i 1308 K.O. Grohote |
| community: | 1313 I 1300 IXO. Gronote |
| Coordinates: | E=482854 , N=4805710 |
| Owner / contact: | Owner: Općina Šolta |
| Heritage status / protection: | Grohote Cultural-Historical site / Z-5862 |
| Use (original): | Residential houses with auxiliary objects |
| Typology: | Residential complex consisting of several houses which |
| | are connected through common courtyards mainly used |
| | for processing agricultural products. Courtyard |
| | contains grapes stone mill, olive stone mill and lime |
| | storage (vapnenica za gašenje vapna). Ground floor is |
| | used as a tavern (konoba), while the living area is placed |
| | on the first floor which is accessed by an external stone |
| Charles to the control of the contro | staircase. |
| Short description | The main building has a ground floor and three floors |
| (ground plan, architectural elements, chronology): | above. Two houses were added along the sides of the main house. The courtyard is placed in front of them, |
| etements, enronotogy). | containing external stone staircase. Ground floor is used |
| | as a tavern (konoba), while the living area is placed on |
| | the floors above. The courtyards were used to process |
| | agricultural products. Grapes and olive stone mill is still |
| | preserved, as well as a small lime storage used to |
| | produce lime. |
| | Buildings are recorded on the Austrian plans made at |
| | the beginning of 19 th century. |
| | |
| | |
| | |
| | |
| Special features: | Preserved original volume and functions (and with |
| special jeans es. | original slates), courtyard, millstones, eaves and vaults |
| | from platy limestone |
| | |
| Platy limestone in elements / | Platy limestone is used mainly on roof surfaces, |
| state of conservation: | pavement, wall cover, benches. |
| | Stone structure of the main house is in good condition |
| | except ground-floor entrance. Also, back side of the |
| Notes | main house is ruin, without floors and roof. |
| Notes: | This house and the courtyard was used to film scenes in |
| Descriptor: | the show <i>Velo misto</i> made by Miljenko Smoje. Ivo Vojnović |
| Descriptor: | IVO VOJNOVIC |

| Date of fieldwork: | 6.9.2014 |
|------------------------------|-----------------------------|
| | |
| | |
| GEOLOGY | |
| Selected limestone elements: | 1 walls |
| | 2 main roof |
| | 5 eaves |
| | 6 corner stones |
| | 7 window frame |
| | 9 doorpost |
| | 11 stairs |
| | 12 outside pavement |
| | 18 stone bordure |
| | 19 vault |
| | 37 window consoles |
| | 38 stair enclose consoles |
| | 39 wall cover |
| | 40 openings (ponare) |
| | 41 grapes stone mill |
| | 42 olive stone mill |
| | 43 lime storage (vapnenica) |
| | 44 bench |
| | 45 chimney |
| | 46 stone game (trilja) |
| Quarries/excavation sites in | |
| neighbourhood: | |
| Notes: | |
| Descriptor: | |
| Date: | |
| | |



 ${\it Illustrative\ enclosure\ to\ the\ Roof\ of\ Rock\ description\ Sheet:}$

1: Topographic map, general




Croatian basic map (HOK):




Ortophoto:




Modern cadastral map:



Historical map Second Military Mapping Survey of Austrian Empire ca. 1830 (revision 1880) 1:2880 obtained from: State Archive – Split



Photodokumentation:























18. Monastery-museum, Blaca, Brač, Croatia


| RoR description number | 3602 |
|--|---|
| CULTURAL HERITAGE | |
| Name (official and common): | Island of Brač, Blaca Hermitage |
| Address (location): | Nerežišća bb, Brač, Croatia |
| Cadastral number, | *34, Nerežišća |
| community: | |
| Coordinates: | E=4794800 , N=502400 |
| Owner / contact: | |
| Heritage status / protection: | Blaca Hermitage / listed as a national built heritage and also was added to the <u>UNESCO</u> <u>World</u> <u>Heritage</u> Tentative List on January 29, 2007 / Z-1553 |
| Use (original): | Sacral monument (original) / Museum (today) |
| Typology: | The Blaca Hermitage is unique monument on the Croatian coast. It was hermitage of the Glagolitic Order (Glagoljica – Croatian ancient alphabet) raised on the steep cliff. Blaca were established by Glagolitic priests from Poljica that fled to island of Brac running away from the Turks. In 1552. they established monastic community and in 1570 they got permission from the bishop to raise monastery and church. They produced wine, honey and other cultures. Wealth of the priests provided them to become world-wide known astronomic observatory. Furniture of Blaca monastery is also very atractive, the church was restored following the baroque patterns. After the departure of last monk, father Nikola Milićević in 1963, the monastery was transformed into museum. |
| Short description (ground plan, architectural elements, chronology): | The Blaca hermitage is located in a long karstic valley on the southern part of the island of Brač. The monastery, completely isolated in an austere site, was built in front of the cave Ljubitovica below high cliffs. It consists of church from the XVII century, apartment buildings and outbuildings, observatories and libraries, all built in limestone. This eremite quarters was established in the sixteenth century. The church is located near the caves. A complex of buildings was reconstructed and modified. |
| Special features: | Blaca Hermitage added to the UNESCO World Heritage Tentative List on January 29, 2007 |

| Platy limestone in elements / state of conservation: | Platy limestone is used mainly on roof surfaces, pavement and eaves, all well preserved. |
|--|--|
| Notes: | |
| Descriptor: | Ivo Vojnović |
| Date of fieldwork: | 15.05.2014 |
| | |
| GEOLOGY | |
| Selected limestone elements: | 1 walls |
| | 2 main roof |
| | 5 eaves 7 window frame |
| | 9 doorpost |
| | 12 outside pavement |
| | 41 grapes stone mill |
| | 48 bee farm/plates for bee houses |
| Quarries/excavation sites in | 2 |
| neighbourhood: | |
| Notes: | |
| Descriptor: | |
| Date: | |




Illustrative enclosure to the Roof of Rock description Sheet:

1: Topographic map, general




Croatian basic map (HOK):



Ortophoto:



Modern cadastral map:




Photodokumentation:
















19. kućice Pod Veli vrh, Korčula, Croatia


| RoR description number | 3855 |
|-------------------------------|---|
| | |
| CULTURAL HERITAGE | |
| Name (official and common): | kućice |
| Address (location): | Pod Veli vrh |
| Cadastral number, | 6159/2, Postrana / Žrnovo - Korčula |
| community: | |
| Coordinates: | E= 549 253 , N= 475 5138 |
| Owner / contact: | Owner (4/8): Marko Curač Košić, Žrnovo bb |
| Heritage status / protection: | not protected |
| Use (original): | Agriculture housing |
| Typology: | Single cell houses |
| Short description | Partialy buried in terrain, set of three houses built in |
| (ground plan, architectural | traditional coastal style are interconnected together, |
| elements, chronology): | forming a small courtyard which is enclosed by |
| | boundary wall. Few meters near the objects since there |
| | is a small quarry inside a parcel, to which only one way |
| | leeds, and that is through common courtyard of these |
| | three houses. |
| | On cadhastral map 1836 (revision 1880) objects are not |
| | visible, although near the parcel there is a significant |
| | widening of the road, probably indication that quarry |
| Constitution | was exploited at the time. |
| Special features: | Preserved interlaced roofs with fine carved gutters, roof |
| | ridge covered with slates, relieving opening from platy |
| | limestone; courtyard quarry. |
| Platy limestone in elements / | Main roofs, courtyard tiling, terrace over water cistern, |
| state of conservation: | relieving opening |
| state of conservation. | All in good state of preservation exept roof ridge |
| | covered in platy limestone, which need refixing. |
| Notes: | F, |
| Descriptor: | Filip Bubalo |
| Date of fieldwork: | 14.4.2014 |
| | |
| GEOLOGY | |

| Selected limestone elements: | 0 walls 1 main roof 2 corner stones 3 gutter 4 roof ridge covered with slates eaves 5 window frame 6 doorpost 7 treshold 8 relieving opening 9 scarp of cistern 10 rim of cistern 11 yard wall |
|---|--|
| Quarries/excavation sites in neighbourhood: | Žrnovo, |
| Notes: | |
| Descriptor: | Filip Bubalo |
| Datum: | |


Illustrative enclosure to the Roof of Rock description Sheet:


ex military map, 1 : 25 000






Ortophoto / satellite photo 2013:







6159/2



Historical map Second Military Mapping Survey of Austrian Empire (ca. 1830) 1:28.800


obtained from: http://mapire.eu/



Photodocumentation:
























20. Donja Nakovana / "U Cvitka", Nakovanj bb, Croatia

| RoR description number | 3952 |
|---|---|
| CULTURAL HERITAGE | |
| | Donja Nakovana / "U Cvitka" |
| Name (official and common): Address (location): | Nakovanj bb |
| Cadastral number, | 49.2 / 49.3 /49.4 / 49.5 / , Orebić |
| community: | 49.2 / 49.3 /49.4 / 49.5 / , Of cold |
| Coordinates: | E= 547 497, N= 4762717 |
| Owner/contact: | Owner: family Lupis, |
| Heritage status / protection: | Nakovana Cultural-Historical site / Z-1423 |
| Use (original): | Residential houses with auxiliary objects |
| Typology: | Two storey houses with dislocated kitchen (konoba), |
| 71 G7 | bread owen (krušna peć), threshing floor and stonemill |
| Short description | Square groundplan, build with processed limestone |
| (ground plan, architectural | blocks and finsihed in lime mortar, inner plastering, |
| elements, chronology): | door and window lintels, eaves, windows with iron |
| | fitings. |
| | There are indications that area around this village was |
| | inhabitated 8000 years ago, but the first menation has |
| | been recorded in 1335. as Nacovalda. Two villages Upper |
| | and Lower Nakovana belonged to the space Trstenice, |
| | administrative units of the Dubrovnik Republic since the |
| | 14th century, when previous settlements formed in two present-day village in the Middle Ages. |
| | Whole area of Nakovana plateau has continuity of life |
| | since Neolithic times until W.W. II., due to movement of |
| | people to the coastal area and emigration. |
| | Village can be seen od cadastral map from 1836 |
| | (revision 1880), with draw in buildings. |
| | Specific culture that made pottery found in nearby |
| | Neolithic caves, was named Nakovana culture. |
| Special features: | Preserved original volume (and with original slates), |
| | courtyard millstone, eaves from platy limestone, and |
| | attached water cistern for common use. |
| Di di li di | |
| Platy limestone in elements / | Platy limestone is used mainly on roof surfaces, |
| state of conservation: | residential and kitchen house, chimneys, pavement, scarp of water cistern, eaves, tables and benches. |
| | Although structure of the most objects is in good state |
| | of preservation, several of them need new and complete |
| | roof reconstruction, while some of the objects just need |
| | remixing of limestone slates |
| Notes: | One of the houses with no roof is a birth place of Ivan |
| | Lupis- the inventor of torpedo. |
| Descriptor: | Filip Bubalo |
| Date of fieldwork: | 7.5.2014 |
| | |


| GEOLOGY | |
|---|--|
| Selected limestone elements: | 0 walls: 1 main roof 2 eaves: 3 window frame 4 doorpost 5 bread owen 6 stairs 7 courtyard pavement 8a crown of water cistern 8b scarp of cistern 9 stonemill 10 vaulted window frame 11 consoles 12 openings (ponare) 13 threshing floor |
| Quarries/excavation sites in neighbourhood: | |
| Notes: | |
| Descriptor: | L. Fuček, N. Oštrić |
| Date: | |

Illustrative enclosure to the Roof of Rock description Sheet:

Topographic map, general (1: 25 000)



Croatian basic map (HOK):




Ortophoto:





Historical map Second Military Mapping Survey of Austrian Empire ca. 1830 (revision 1880) 1:28.800 obtained from: State Archive – Split



Historical photography (1905.)



Photodokumentation:












Architectural drawings:









Author of architectural drawings: d.i.a Željko Peković


Description sheet prepared by Filip Bubalo / June 2014

21. Štala/stable - Bobana lazi, Aleja kod Groblja / Arbored walk by the cemetery of St. Roko, Croatia

| RoR description number | 3861 |
|--------------------------------------|--|
| | |
| CULTURAL HERITAGE | IX. N. () IX. D. I. IX. IX. IX. IX. IX. IX. IX. IX. IX. |
| Name (official and common): | Štala/stable - Bobana lazi |
| Address (location): | Aleja kod Groblja / Arbored walk by the cemetery of St. Roko |
| Cadastral number, | 1769/1, Vela Luka |
| community: | |
| Coordinates: | E= 518075 , N= 4757874 |
| Owner / contact: | Owner: Denis (dec.) and Jela Žuvela |
| Heritage status / protection: | no protection |
| Use (original): | Stable (for donkeys) |
| Typology: | Single cell house with added smaller one (demolished) |
| Short description | Typical dry stone wall stable with rectangular floor |
| (ground plan, architectural | plan and |
| elements, chronology): | inner concrete divider wall for keeping donkey. |
| | By the side wall there is a smaller annex (demolished), |
| | and in front of the house there are two small eaves, |
| | and a vaulted water cistern. |
| | Object is one of the 20 almost identical dwellings that |
| | were built surely after 1880, because thera are not on |
| | Austrian Empire cadastral map. There is unconfirmed |
| | story, that houses serving for agricultural use of local |
| | community are built between two World Wars, as |
| | reaction of locals to the a new road to the cemetery. |
| Special features: | Preserved original volume; roof has been rebuilt by the |
| | owner two decades before (in great condition); two |
| | small eaves roofs on each side of the entrance |
| Platy limestone in elements / | Main gable roof, eaves roofs, doorpost, terrace around |
| state of conservation: | water cistern |
| v | Main object is in good state of preservation, but two |
| | smaller eaves roofs need remixing of plates. |
| Notes: | |
| Descriptor: | Filip Bubalo |
| Date of fieldwork: | 14.4.2014 |
| CEOLOGY | |
| GEOLOGY Selected limestone elements: | A swaller |
| Selectea limestone elements: | 0 walls: |
| | 1 main roof |
| | 2 eaves roofs |
| | 3 corner stones |
| | 4 doorpost (wooden and platy limestone) |
| | 5 window frame |
| | 6 wooden construction beams |
| | 6a lintel (wooden) |

| | 7 divider wall - of concrete 8 outside pavement 9 yard wall 10 cistern |
|---|---|
| Quarries/excavation sites in neighbourhood: | Taken from nearby "lazi" (terraced vineyards), surface quarries about 1km air distance. Local people still remember, when donkeys loaded with platy limestone were brought to the site. |

llustrative enclosure to the Roof of Rock description Sheet:



Croatian basic map (HOK):




Ortophoto:



Modern cadastral map:



Historical map
Second Military Mapping Survey of Austrian Empire ca. 1830 (revision 1880)
1:28.800



Historical photography: Situation circa. 1950



Photodocumentation:



















Architectural drawings:





Author of architectural drawings: Miše Renić

Description sheet prepared by Filip Bubalo 24. 05. 2014

22. "Lalića tower house", Mostarska Vrata, Ljubuški/Lalića kula, Mostarska Vrata b.b., 88320 Ljubuški, Bosnia and Herzegovina

| RoR description number | HERCEGOVAČKI KRŠ / HERZEGOVINIAN KARST |
|--|---|
| CULTURAL HERITAGE | |
| Name (official and common): | "Lalića tower house", Mostarska Vrata, Ljubuški/Lalića kula |
| Address (location): | Mostarska Vrata b.b., 88320 Ljubuški |
| Cadastral number, community: | c. p. 2718, c. m. Mostarska Vrata |
| Coordinates: | y=6464885,67 x=4784197.21 |
| Owner / contact: | Obitelj Ćerimović, M. Selimovića 12, Sarajevo, +387 62 346628 |
| Heritage status / protection: | National monument |
| Use (original): | Housing and defense property |
| Typology: | Ottoman fortified residential tower |
| Short description | The tower is a tall building with a ground floor and two |
| (ground plan, architectural | upper floors. The base is rectangular 6:00 x 6.35m. |
| elements, chronology): | Height east wall is 8.50m northwest 7.50m. The total height of the tower is 10.35m. |
| Special features: | Access staircase has three stone steps leading to the entrance to the tower. Admission to the tower is on the west wall of the tower at its southern corner. Front doors are accentuated with stone frame with two vertical pillars and stone arch over them. |
| Platy limestone in elements / state of conservation: | Roof of platy limestone, completely renovated in the early 21st ct. |
| Notes: | |
| Descriptor: | Radoslav Dodig |
| Date of fieldwork: | 4.6. 2013. and 28.8.2013. |
| GEOLOGY | |
| Selected limestone elements: | 0 walls: 1 main roof: 2 front door 3 stairs 4 cistern 5 loophole 6 wall shelf |
| Quarries/excavation sites in neighbourhood: | Mostarska Vrata (Vicinity of Ljubuški); Crveni Grm |
| Notes: | |
| 1101001 | <u> </u> |


| Descriptor: | |
|-------------|--|
| Datum: | |
| | |

Illustrative enclosure to the Roof of Rock description Sheet:

Topographic map, general: 1:700.000




Topographic map, 1:25.000, Mostar 574-2-3





Cadastral map:








Photodokumentation: Lalić Tower, Mostarska Vrata, Front door








Photodokumentation: Lalić Tower, Mostarska Vrata, 1901.



Lalić Tower, 1975.






Lalića Tower, Loophole




Photodokumentation: Lalića tower, Wall shelf



Fieldwork, 17.6.2014 (photo R. Dodig)






Description sheet prepared by Radoslav Dodig, 28. 06. 2014

23. "Bišćević House", Bišćevića ulica 13, Mostar, Bosnia and Herzegovina


| RoR description number | HERCEGOVAČKI KRŠ / HERZEGOVINIAN KARST |
|-------------------------------|--|
| CULTURAL HERITAGE | |
| Name (official and common): | "Bišćević House", Mostar |
| Address (location): | Bišćevića ulica 13 |
| Cadastral number, | k. č. 3214-3215, k.o. Mostar |
| community: | R. C. 3217-3213, R.O. WIOSTAI |
| Coordinates: | y=6485241.62 x=4799564.75 |
| Owner / contact: | Owner: Family Bišćević and Lakišić, 387 36 552 197 |
| Heritage status / protection: | National monument |
| Use (original): | Dwelling house and tourist object |
| Typology: | Ottoman residential complex |
| Short description | The complex has remained relatively unchanged from |
| (ground plan, architectural | 17. to 20. ct. and consists of two parts: selamluk (male |
| elements, chronology): | yard or part of the house for the reception of guests and |
| | business talks) and <i>haremluk</i> (women's or family's |
| | courtyard, an intimate part of the building). The |
| | material used for building houses a local quarry stone. |
| | The wood is used for the pillars, floor and roof |
| | construction, as well as doors and windows. |
| Special features: | The house is very boldly composite piece of residential |
| | architecture from the Ottoman period, with divanhana |
| | (room for talks), a garden and a protruding part with |
| | tall columns above the Neretva. |
| Platy limestone in elements / | Great part of Roof is reconstruction in 20. ct. from local |
| state of conservation: | quarries of platy limestones. |
| | One part is not in good state of preservation. |
| Notes: | |
| Descriptor: | Radoslav Dodig |
| Date of fieldwork: | 3.6. 2013. and 27.8.2013. |
| GEOLOGY | |
| Selected limestone elements: | 0 walls: |
| | 1 main roof: |
| | 2 small roof: |
| | 3 small roof |
| | A ontrongo goto |
| | 4 entrance gate 5 porch (doksat) |
| | 6 courtyard floor |
| | o courty are rivor |
| Quarries/excavation sites in | Podveležje (Vicinity of Mostar); Ortiješ, Mostar |
| neighbourhood: | |
| | |
| Notes: | |

| Descriptor: | |
|-------------|--|
| Datum: | |
| | |

Illustrative enclosure to the Roof of Rock description Sheet:




Topographic map, 1:25.000, Mostar 574-2-3, 1976.




Ortophoto / by Ecoplan, Mostar, 2009.



Geodetic image of Mostar, 1886.




Cadastral map:




3214-3215, c.c. Mostar, 1:500

Historical photography: 1965.



Look at Bišćević House, Mostar



MOSTAR, Bišćević House





MOSTAR, Bišćević House, Small roofs


Photodokumentation:








MOSTAR, Bišćević House, Entrance, Porch and Courtyard Floor



MOSTAR, Bišćević House, Ground Plan and Roofs

Construction drawings, Ana Tolić, Ljubuški




Description sheet prepared by Radoslav Dodig, Ljubuški, 15. 06. 2014


24. "Velagić Mill"/Velagića mlinica, *Velagićevina b.b.*, 88201 Blagaj, Bosnia and Herzegovina

| RoR description number | HERCEGOVAČKI KRŠ / HERZEGOVINIAN KARST |
|--|--|
| CULTURAL HERITAGE | |
| Name (official and common): | "Velagić Mill"/Velagića mlinica, Blagaj |
| Address (location): | Velagićevina b.b., 88201 Blagaj |
| Cadastral number, community: | c.č. 1447, c.m. Blagaj |
| Coordinates: | y=6492377,80 x=4790250.04 |
| Owner / contact: | Owner: Family Velagić, 88201 Blagaj, 387 062 532 518 |
| Heritage status / protection: | National monument |
| Use (original): | Ethnological monument/Mill |
| Typology: | Ottoman economic complex |
| Short description | Facility mills has an irregular rectangular shape with |
| (ground plan, architectural elements, chronology): | dimensions: width on the north side is 6.83 m and 6.15 m in the south, while the length of 17.62 m. Under the first part of rammed earth. The walls are made of crushed stone thickness of 55-60 cm. The first part was living millers, while the second part contained five mills properly distributed. |
| Special features: | On the west wall, the inner side of the room where the mills, there is a stone fireplace whose stone chimney exits the roof. |
| Platy limestone in elements / state of conservation: | Roof of platy limestone. Reconstruction from 20. ct. |
| Notes: | |
| Descriptor: | Radoslav Dodig |
| Date of fieldwork: | 3.6. 2013. and 27.8.2013. |
| GEOLOGY | |
| Selected limestone elements: | 0 walls: 1 main roof (west) 1 main roof (east) 2 Way to the mill 3 Entrance to the mill 4 Hearth 5 Millstone |
| Quarries/excavation sites in neighbourhood: | Podveležje (Vicinity of Mostar); Ortiješ, Mostar |
| Notes: | |


| Descriptor: | |
|-------------|--|
| Datum: | |
| | |

Illustrative enclosure to the Roof of Rock description Sheet:






Ortophoto / Microsoft Search Map 2011



Cadastral map:



Photodocumentation

Blagaj, Mill on the west side



Blagaj, Mill on the east side



Photodokumentation:




Blagaj, Entrance to the mill






Blagaj, Millstone





Architectural drawings, Ana Tolić




Description sheet prepared by Radoslav Dodig, 20. 06. 2014

25. "Gavrankapetanović Tower", Glavna kula, Počitelj b.b., 88305 Počitelj, B&H, Bosnia and Herzegovina


| RoR description number | HERCEGOVAČKI KRŠ / HERZEGOVINIAN KARST |
|-------------------------------|--|
| CHI THE AT THE DECADE | |
| CULTURAL HERITAGE | |
| Name (official and common): | "Gavrankapetanović Tower", Glavna kula |
| Address (location): | Počitelj b.b., 88305 Počitelj, B&H |
| Cadastral number, | c. č. 2585 c.m. Počitelj |
| community: | (ABOFBA 0.) ABB (00A 3.) |
| Coordinates: | y=6478573,06 x=4776802,36 |
| Owner / contact: | Turistička zajednica Hercegovačko-neretvanske |
| | županije, dr. Ante Starčevića b.b., Mostar, +387 36 355 090 |
| Heritage status / protection: | National monument |
| Use (original): | Historical monument /Defensive tower |
| Typology: | Ottoman fortification system |
| Short description | The fort of Počitelj was built in the 15. ct. Central tower |
| (ground plan, architectural | has an octagonal base with additions from the Ottoman |
| elements, chronology): | period, 17-18. ct. |
| | |
| | |
| Special features: | Stylistically, the residential architecture of city is a blend |
| | of Mediterranean and Oriental elements with certain |
| | local features. In Počitelj almost all buildings were built |
| Di di | of stone |
| Platy limestone in elements / | Platy limestone in roof/ Reconstruction from 1971 and |
| state of conservation: | 2001. |
| Notes: | |
| Descriptor: | Radoslav Dodig |
| Descriptor. | Rauosiav Douig |
| Date of fieldwork: | 3.6. 2013. and 27.8.2013. |
| | |
| | |
| GEOLOGY | |
| Selected limestone elements: | 0 walls: |
| | 1 Roof of the main Tower |
| | 2 Southeast entrance |
| | 3 Western part of the tower 4 Door belvedere |
| | |
| | 5 Entrance to the tower 6 Window on the south side |
| | o white on the south side |
| Quarries/excavation sites in | Podveležje (Vicinity of Mostar); Dretelj, Čapljina |
| neighbourhood: | 1 ouvelezje (vielinty of mostar), Dietelj, Capijina |
| | |
| Notes: | |
| | |

| Descriptor: | |
|-------------|--|
| Datum: | |
| | |


Illustrative enclosure to the Roof of Rock description Sheet:
2: Počitelj b.b., 88305 Počitelj



Topographic map Mostar 574-2-3, 1:25.000





Ortophoto / Microsoft search Map





Plan of Počitelj, Kriegsarchiv Wien, 1783. Cadastral Map





Počitelj, Rudolf von Ottenfeld, Die österr:-ung. Monarchie in Wort und Bild, 1901.

Historic gravure from 1901.

Photodocumentation



Počitelj, Main Tower



Photodokum entation



Počitelj, Southeast entrance



Počitelj, western part of the Tower

Photodocumentation




Počitelj, Door belvedere




Počitelj, Entrance to the Tower

Photodocumentation




Počitelj, window on the south side

Fieldwork, 16.6.2014 (photo R. Dodig)







Architectural drawings: Počitelj, Dž. Čelić, 1960.



Ground plan of the main tower






Description sheet prepared by Radoslav Dodig, 24. 06. 2014

26. "Čaršijska mosque", Blagaj/Careva džamija, Ada b.b., 88360 Stolac, Bosnia and Herzegovina

| Short description (ground plan, architectural elements, chronology): Special features: The mosque complex consists of a mosque, cistern, the harem of the mosque, a fountain in the portal axle, gusulhana and harem walls. It is one of the largest BH mosque built in the 16th century. Its size measuring 18.30 x 15.30 m Special features: The mosque is in the interior had 11 poles, five relied on by the central ceiling beams and 6 columns on which he relied mahvil. Dimensions columns were 20 cm x 20 cm to 25 cm x 25 cm. Platy limestone in elements / state of conservation: Roof of platy limestone on the mosque and on other objects. It's fully reconstructed in 2006 Notes: Descriptor: Radoslav Dodig | RoR description number | HERCEGOVAČKI KRŠ / HERZEGOVINIAN KARST | |
|---|---|--|--|
| Name (official and common): Address (location): Ada b.b., 88360 Stolac Cadastral cummunity: Coordinates: Owner / contact: National monument Use (original): Typology: Short description (ground plan, architectural elements, chronology): The mosque with minaret Use entral ceiling beams and 6 columns on which he relied mahvil. Dimensions columns were 20 cm x 20 cm to 25 cm x 25 cm. Platy limestone in elements: Descriptor: Notes: Descriptor: Radoslav Dodig Date of fieldwork: O walls: 1 main roof of mosque: 2 minaret 3 main entrance of the mosque 4 cistern 5 fountain (shadrvan) 6 muslim tombstone | | | |
| Add b.b., 88360 Stolac Cadastral number, c. p. 2/219, c.m. Stolac community: Coordinates: Owner / contact: Medžlis Islamske zajednice Stolac, Stolac +387 36 584 580 Heritage status / protection: Use (original): Typology: Short description (ground plan, architectural elements, chronology): Special features: The mosque complex consists of a mosque, cistern, the harem of the mosque, a fountain in the portal aske, gusulhana and harem walls. It is one of the largest BH mosque built in the 16th century. Its size measuring 18.30 x 15.30 m The mosque is in the interior had 11 poles, five relied on by the central ceiling beams and 6 columns on which he relied mahvil. Dimensions columns were 20 cm x 20 cm to 25 cm x 25 cm. Platy limestone in elements / Roof of platy limestone on the mosque and on other objects. It's fully reconstructed in 2006 Notes: Descriptor: Radoslav Dodig Date of fieldwork: 0 walls: 1 main roof of mosque: 2 minaret 3 main entrance of the mosque 4 cistern 5 fountain (shadrvan) 6 muslim tombstone | | "\(\tilde{\C}_{\tilde{\C}}\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\ | |
| Cadastral community: Coordinates: Owner / contact: Wed2lis Islamske zajednice Stolac, Stolac +387 36 584 580 Heritage status / protection: Use (original): Typology: Short description (ground plan, architectural elements, chronology): Special features: The mosque complex consists of a mosque, cistern, the harem of the mosque, a fountain in the portal axle, gusulhana and harem walls. It is one of the largest BH mosque built in the 16th century. Its size measuring 18.30 x 15.30 m The mosque is in the interior had 11 poles, five relied on by the central ceiling beams and 6 columns on which he relied mahvil. Dimensions columns were 20 cm x 20 cm to 25 cm x 25 cm. Platy limestone in elements / state of conservation: Notes: Descriptor: Radoslav Dodig Date of fieldwork: 0 walls: 1 main roof of mosque: 2 minaret 3 main entrance of the mosque 4 cistern 5 fountain (shadrvan) 6 muslim tombstone | | | |
| Coordinates: Coordinates: V=6497068.38 x=4770950,40 Medžlis Islamske zajednice Stolac, Stolac +387 36 584 580 Heritage status / protection: Use (original): Typology: Ottoman mosque with minaret The mosque complex consists of a mosque, cistern, the harem of the mosque, a fountain in the portal axle, gusulhana and harem walls. It is one of the largest BH mosque built in the 16th century. Its size measuring 18.30 x 15.30 m Special features: The mosque is in the interior had 11 poles, five relied on by the central ceiling beams and 6 columns on which he relied mahvil. Dimensions columns were 20 cm x 20 cm to 25 cm x 25 cm. Platy limestone in elements / state of conservation: Notes: Descriptor: Radoslav Dodig Date of fieldwork: 3.6. 2013. and 27.8.2013. GEOLOGY Selected limestone elements: 1 main roof of mosque: 2 minaret 3 main entrance of the mosque 4 cistern 5 fountain (shadrvan) 6 muslim tombstone | | , | |
| Special features: Y=6497068.38 x=4770950,40 | · · · · · · · · · · · · · · · · · · · | c. p. 2/219, c.m. Stolac | |
| Medžlis Islamske zajednice Stolac, Stolac +387 36 584 580 Heritage status / protection: Use (original): Typology: Short description (ground plan, architectural elements, chronology): Special features: The mosque complex consists of a mosque, cistern, the harem of the mosque, a fountain in the portal axle, gusulhana and harem walls. It is one of the largest BH mosque built in the 16th century. Its size measuring 18.30 x 15.30 m The mosque is in the interior had 11 poles, five relied on by the central ceiling beams and 6 columns on which he relied mahvil. Dimensions columns were 20 cm x 20 cm to 25 cm x 25 cm. Platy limestone in elements / state of conservation: Notes: Descriptor: Radoslav Dodig Date of fieldwork: 3.6. 2013. and 27.8.2013. GEOLOGY Selected limestone elements: 0 walls: 1 main roof of mosque: 2 minaret 3 main entrance of the mosque 4 cistern 5 fountain (shadrvan) 6 muslim tombstone | | v=6497068 38 v=4770950 40 | |
| Heritage status / protection: Use (original): Typology: Short description (ground plan, architectural elements, chronology): Special features: The mosque complex consists of a mosque, cistern, the harem of the mosque, a fountain in the portal axle, gusulhana and harem walls. It is one of the largest BH mosque built in the 16th century. Its size measuring 18.30 x 15.30 m The mosque is in the interior had 11 poles, five relied on by the central ceiling beams and 6 columns on which he relied mahvil. Dimensions columns were 20 cm x 20 cm to 25 cm x 25 cm. Platy limestone in elements / state of conservation: Notes: Descriptor: Radoslav Dodig Date of fieldwork: 3.6. 2013. and 27.8.2013. GEOLOGY Selected limestone elements: 0 walls: 1 main roof of mosque: 2 minaret 3 main entrance of the mosque 4 cistern 5 fountain (shadrvan) 6 muslim tombstone | | | |
| Use (original): Religious needs /mosque Typology: Ottoman mosque with minaret The mosque complex consists of a mosque, cistern, the harem of the mosque, a fountain in the portal axle, gusulhana and harem walls. It is one of the largest BH mosque built in the 16th century. Its size measuring 18.30 x 15.30 m Special features: The mosque is in the interior had 11 poles, five relied on by the central ceiling beams and 6 columns on which he relied mahvil. Dimensions columns were 20 cm x 20 cm to 25 cm x 25 cm. Platy limestone in elements / Roof of platy limestone on the mosque and on other objects. It's fully reconstructed in 2006 Notes: Descriptor: Radoslav Dodig Date of fieldwork: 3.6. 2013. and 27.8.2013. GEOLOGY Selected limestone elements: 1 main roof of mosque: 2 minaret 3 main entrance of the mosque 4 cistern 5 fountain (shadrvan) 6 muslim tombstone | <i>e ,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,</i> | | |
| Religious needs /mosque | Heritage status / protection: | National monument | |
| Short description (ground plan, architectural elements, chronology): Special features: The mosque complex consists of a mosque, cistern, the harem of the mosque, a fountain in the portal axle, gusulhana and harem walls. It is one of the largest BH mosque built in the 16th century. Its size measuring 18.30 x 15.30 m The mosque is in the interior had 11 poles, five relied on by the central ceiling beams and 6 columns on which he relied mahvil. Dimensions columns were 20 cm x 20 cm to 25 cm x 25 cm. Platy limestone in elements / state of conservation: Notes: Descriptor: Radoslav Dodig Date of fieldwork: 3.6. 2013. and 27.8.2013. GEOLOGY Selected limestone elements: 0 walls: 1 main roof of mosque: 2 minaret 3 main entrance of the mosque 4 cistern 5 fountain (shadrvan) 6 muslim tombstone | | Religious needs /mosque | |
| harem of the mosque, a fountain in the portal axle, gusulhana and harem walls. It is one of the largest BH mosque built in the 16th century. Its size measuring 18.30 x 15.30 m Special features: The mosque is in the interior had 11 poles, five relied on by the central ceiling beams and 6 columns on which he relied mahvil. Dimensions columns were 20 cm x 20 cm to 25 cm x 25 cm. Platy limestone in elements / Roof of platy limestone on the mosque and on other objects. It's fully reconstructed in 2006 Notes: Descriptor: Radoslav Dodig 3.6. 2013. and 27.8.2013. GEOLOGY Selected limestone elements: 1 main roof of mosque: 2 minaret 3 main entrance of the mosque 4 cistern 5 fountain (shadrvan) 6 muslim tombstone | Typology: | Ottoman mosque with minaret | |
| gusulhana and harem walls. It is one of the largest BH mosque built in the 16th century. Its size measuring 18.30 x 15.30 m Special features: The mosque is in the interior had 11 poles, five relied on by the central ceiling beams and 6 columns on which he relied mahvil. Dimensions columns were 20 cm x 20 cm to 25 cm x 25 cm. Platy limestone in elements / state of conservation: Descriptor: Radoslav Dodig Date of fieldwork: 3.6. 2013. and 27.8.2013. GEOLOGY Selected limestone elements: 0 walls: 1 main roof of mosque: 2 minaret 3 main entrance of the mosque 4 cistern 5 fountain (shadrvan) 6 muslim tombstone | Short description | The mosque complex consists of a mosque, cistern, the | |
| mosque built in the 16th century. Its size measuring 18.30 x 15.30 m Special features: The mosque is in the interior had 11 poles, five relied on by the central ceiling beams and 6 columns on which he relied mahvil. Dimensions columns were 20 cm x 20 cm to 25 cm x 25 cm. Platy limestone in elements / State of conservation: Notes: Descriptor: Radoslav Dodig Date of fieldwork: 3.6. 2013. and 27.8.2013. GEOLOGY Selected limestone elements: 1 main roof of mosque: 2 minaret 3 main entrance of the mosque 4 cistern 5 fountain (shadrvan) 6 muslim tombstone | | | |
| 18.30 x 15.30 m Special features: The mosque is in the interior had 11 poles, five relied on by the central ceiling beams and 6 columns on which he relied mahvil. Dimensions columns were 20 cm x 20 cm to 25 cm x 25 cm. Platy limestone in elements / state of conservation: Roof of platy limestone on the mosque and on other objects. It's fully reconstructed in 2006 | elements, chronology): | | |
| The mosque is in the interior had 11 poles, five relied on by the central ceiling beams and 6 columns on which he relied mahvil. Dimensions columns were 20 cm x 20 cm to 25 cm x 25 cm. Platy limestone in elements / state of conservation: Notes: Descriptor: Radoslav Dodig Date of fieldwork: 3.6. 2013. and 27.8.2013. GEOLOGY Selected limestone elements: 1 main roof of mosque: 2 minaret 3 main entrance of the mosque 4 cistern 5 fountain (shadrvan) 6 muslim tombstone | | | |
| by the central ceiling beams and 6 columns on which he relied mahvil. Dimensions columns were 20 cm x 20 cm to 25 cm x 25 cm. Platy limestone in elements / Roof of platy limestone on the mosque and on other objects. It's fully reconstructed in 2006 Notes: Descriptor: Radoslav Dodig Date of fieldwork: 3.6. 2013. and 27.8.2013. GEOLOGY Selected limestone elements: 0 walls: 1 main roof of mosque: 2 minaret 3 main entrance of the mosque 4 cistern 5 fountain (shadrvan) 6 muslim tombstone | G . 1.C . | | |
| relied mahvil. Dimensions columns were 20 cm x 20 cm to 25 cm x 25 cm. Platy limestone in elements / Roof of platy limestone on the mosque and on other objects. It's fully reconstructed in 2006 Notes: Descriptor: Radoslav Dodig Date of fieldwork: 3.6. 2013. and 27.8.2013. GEOLOGY Selected limestone elements: 1 main roof of mosque: 2 minaret 3 main entrance of the mosque 4 cistern 5 fountain (shadrvan) 6 muslim tombstone | Special features: | | |
| to 25 cm x 25 cm. Platy limestone in elements / Roof of platy limestone on the mosque and on other objects. It's fully reconstructed in 2006 Notes: Descriptor: Radoslav Dodig Date of fieldwork: 3.6. 2013. and 27.8.2013. GEOLOGY Selected limestone elements: 1 main roof of mosque: 2 minaret 3 main entrance of the mosque 4 cistern 5 fountain (shadrvan) 6 muslim tombstone | | | |
| Roof of platy limestone on the mosque and on other state of conservation: Roof of platy limestone on the mosque and on other objects. It's fully reconstructed in 2006 | | | |
| state of conservation: Objects. It's fully reconstructed in 2006 Notes: Descriptor: Radoslav Dodig 3.6. 2013. and 27.8.2013. GEOLOGY Selected limestone elements: 1 main roof of mosque: 2 minaret 3 main entrance of the mosque 4 cistern 5 fountain (shadrvan) 6 muslim tombstone | Platy limestone in elements / | | |
| Notes: Descriptor: Radoslav Dodig Date of fieldwork: 3.6. 2013. and 27.8.2013. GEOLOGY Selected limestone elements: 1 main roof of mosque: 2 minaret 3 main entrance of the mosque 4 cistern 5 fountain (shadrvan) 6 muslim tombstone | | | |
| Descriptor: Date of fieldwork: 3.6. 2013. and 27.8.2013. GEOLOGY Selected limestone elements: 1 main roof of mosque: 2 minaret 3 main entrance of the mosque 4 cistern 5 fountain (shadrvan) 6 muslim tombstone | 3 | | |
| Date of fieldwork: 3.6. 2013. and 27.8.2013. GEOLOGY Selected limestone elements: 0 walls: 1 main roof of mosque: 2 minaret 3 main entrance of the mosque 4 cistern 5 fountain (shadrvan) 6 muslim tombstone | Notes: | | |
| GEOLOGY Selected limestone elements: 0 walls: 1 main roof of mosque: 2 minaret 3 main entrance of the mosque 4 cistern 5 fountain (shadrvan) 6 muslim tombstone | Descriptor: | Radoslav Dodig | |
| Selected limestone elements: 0 walls: 1 main roof of mosque: 2 minaret 3 main entrance of the mosque 4 cistern 5 fountain (shadrvan) 6 muslim tombstone | Date of fieldwork: | 3.6. 2013. and 27.8.2013. | |
| Selected limestone elements: 0 walls: 1 main roof of mosque: 2 minaret 3 main entrance of the mosque 4 cistern 5 fountain (shadrvan) 6 muslim tombstone | CFOLOGY | | |
| 1 main roof of mosque: 2 minaret 3 main entrance of the mosque 4 cistern 5 fountain (shadrvan) 6 muslim tombstone | | 0 walls: | |
| 2 minaret 3 main entrance of the mosque 4 cistern 5 fountain (shadrvan) 6 muslim tombstone | Secreta intestone elements. | · · · · · · · · · · · · · · · · · · · | |
| 4 cistern 5 fountain (shadrvan) 6 muslim tombstone | | | |
| 5 fountain (shadrvan) 6 muslim tombstone | | 3 main entrance of the mosque | |
| 5 fountain (shadrvan) 6 muslim tombstone | | 4 cistern | |
| 6 muslim tombstone | | | |
| Quarries/excavation sites in Podveležje (Vicinity of Mostar); Ortiješ, Mostar | | | |
| ~ = 0 m 0 m 0 m 1 m | Ouarries/excavation sites in | Podveležie (Vicinity of Mostar): Ortiieš. Mostar | |
| | neighbourhood: | J (| |
| Notes: | Notes: | | |

| Descriptor: | |
|-------------|--|
| Datum: | |
| | |

Illustrative enclosure to the Roof of Rock description Sheet:




Topographic map, 1.25.000, Mostar 574-2-3




Ortophoto / Microsoft Search Map





Photodokumentation: Sketch of Stolac, Kriegsarchiv Wien, ca. 1900.



Stolac, 1917., unknown author



Photodokumentation:

Photodokumentation: Čaršijska mosque, Stolac





Photodokumentation: Čaršijska mosque, minaret



Main entrance of the mosque



Photodokumentation: Cistern in front of mosque




Fountain (shadrvan)






Fieldwork, 5.6.2014 (photo R.Dodig)


Architectural drawings: Ana Tolić dia Complex of Čaršijska mosque, ground plan




Complex of Čaršijska mosque, roofs



Architectural drawings: Ana Tolić dia View of the mosque



Architectural drawings: Ana Tolić dia View of the mosque



Description sheet prepared by Radoslav Dodig, 27. 06. 2014