





## RoofOfRock

Limestone as the common denominator of natural and cultural heritage along the karstified part of the Adriatic coast

## **CULTURAL HERITAGE AND LIMESTONE**

Appendix 3.I.3

Final report for the project area in Slovenia (Kras)

Annex 3.I.3.1
Representative buildings

Neža Čebron Lipovec, Mitja Guštin

June 2015







Descriptor	Neža Čebron	Lipovec, Mi	tja Guštin, Bož	o Premrl				
Date	4.6.2013	4.6.2013						
NUMBER OF OBJECT IN ROR DATABASE:	2001	Status as heritage:	Local monument	EŠD:	7338			
NAME OF BUILDING (OFFICIAL AND LOCAL):	Pri Blaževih							
ADDRESS AND LOCATION:	Gorenje pri D	ivači 14						
TYPE:	One flor farm	house with	n added kitcher	n ("spahn	jenca")"			
SHORT DESCRIPTION OF BUILDING (GROUNDPLAN, ELEMENTS, CHRONOLOGY):	Typical Karstic home with walled farmyard ("borjač"). House has two drips, added kitchen ("spahnjenca") with four-sixth ground plan and an oven with triangular drip.  Homestead is already visible on Franciscan cadastral map from 1818, while some other buildings in village have cut-in dates from beginning of the 18th century.							
USE (ORIGINAL):	Till 1956 dwe	lling house						
PLATY LIMESTONE PRESENT IN: (AND THEIR STATE OF CONSERVATION):	are covered pavement (in	with škrl nside »škrle ace around	ed kitchen ("sp e. Jutting r e«; outside »; water cistern.	roof ove šeliž«), s	r entrance,			
SPECIFIC OBSERVATIONS:	Preserved original volume and construction, preserved historic arrangement of rooms, added kitchen ("spahnjenca") with bread oven.							
QUARRY/EXTRACTION SITE IN THE AREA:	Gabričje; Pri Rebčevih (Jakob and Ivan Rebec) – Gorenje 8							
CONTACT/OWNER:	Mr. Grželj, 04	1 225 283						

NUMBER OF OBJECT IN ROR DATABASE:	2002	Status as heritage:	Local Monument	EŠD:	7338	
NAME OF BUILDING (OFFICIAL AND LOCAL):	Assumption	n Church in C	Gura			
ADDRESS AND LOCATION:	Plešivica pr	i Povirju ("G	ura pri Povirju	ı")		
TYPE:	Sacral					
SHORT DESCRIPTION OF BUILDING (GROUNDPLAN, ELEMENTS, CHRONOLOGY):	Built in 16th c. During the first renovation were built a new presbytery and an entrance shed (between 1642 and 1647). Baroque modernisation at the end of 17th and in 18th c. Bell tower from 1836.					
USE (ORIGINAL):	Church					
PLATY LIMESTONE PRESENT IN: (AND THEIR STATE OF CONSERVATION):	Western pa	art of the bu	laty limeston ilding is dama g wooden roo arby.	ged by the		
SPECIFIC OBSERVATIONS:	Preserved original volume and construction, preserved historic arrangement of architecture.  Only church on Carst, covered entirely by "škrle".					
QUARRY/EXTRACTION SITE IN THE AREA:	Povir ? > Jurkovšek					
CONTACT/OWNER:	priest Sand from Povir	di Škapin iz	Sežane; cont	act also Fr	anc Škrinjar	

NUMBER OF OBJECT IN ROR DATABASE:	2003	Status as heritage:	Local Monument	EŠD:	746	
NAME OF BUILDING (OFFICIAL AND LOCAL):	Assumption	n Church				
ADDRESS AND LOCATION:	Šmarje pri S	Sežani				
TYPE:	Sacral					
SHORT DESCRIPTION OF BUILDING (GROUNDPLAN, ELEMENTS, CHRONOLOGY):	The single-nave church with long presbytery, built in 1502 in late gothic style. Later baroquised, with remodelled bell – gable (1668) and added entrance shed.  Above entrance inscription M\CCCCC\Y = 1502 (Y is not "V" (five), but two "I" = II = 2)  Complex surrounded with wall and porton (with year 18M?8)					
USE (ORIGINAL):	Church					
PLATY LIMESTONE PRESENT IN: (AND THEIR STATE OF CONSERVATION):	Roof covere		e"; stone floc	or in church		
SPECIFIC OBSERVATIONS:	Black limes	tone (glažev	ec; friable, no	t lasting);		
	On west portal stonemasons' signs; signature of Anže Rojina (M.A.R. = magister Anže Rojina); crosses on the plaster					
CONTACT/OWNER:	RKC					

NUMBER OF OBJECT IN ROR DATABASE:	2004	Status as heritage:	Local monument	EŠD:	3780	
NAME OF BUILDING (OFFICIAL AND LOCAL):	St. Eliah Chu	rch				
ADDRESS AND LOCATION:	Kopriva					
TYPE:	Sacral					
SHORT DESCRIPTION OF BUILDING (GROUNDPLAN, ELEMENTS, CHRONOLOGY):	baroque styl	e begun in ). Bell towe	ve church with 3, 1802 and ended i r added in 1852- f of 19 <sup>th</sup> c.	n 1823	(constructor	
USE (ORIGINAL):	Church					
PLATY LIMESTONE PRESENT IN: (AND THEIR STATE OF CONSERVATION):	Roof of presbytery covered with <i>skrle</i> .  All in good state of preservation.					
SPECIFIC OBSERVATIONS:	Inside the church »paleontological museum«					
CONTACT/OWNER:	RKC					

NUMBER OF OBJECT IN ROR DATABASE:	2005	Status as heritage:	Local monument	EŠD:	94		
NAME OF BUILDING (OFFICIAL AND LOCAL):	Škrateljnov	ra domačija					
ADDRESS AND LOCATION:	Kraška cest	a 26, Divača					
TYPE:	profane						
SHORT DESCRIPTION OF BUILDING (GROUNDPLAN, ELEMENTS, CHRONOLOGY):	Dominant "closed" homestead, originating from the 17th century.  L-shaped homestead with double (?) spahnjenca, stable (renovated, extended) and shed (renovated, extended), cistern, new scarp of dry wall, stone gutter.						
USE (ORIGINAL):	Till 1956 dv	velling house	9				
PLATY LIMESTONE PRESENT IN: (AND THEIR STATE OF CONSERVATION):		ain part and state of pres	oven are cove	ered with "šl	krle".		
SPECIFIC OBSERVATIONS:	Preserved original volume and construction, preserved historic arrangement of rooms.  Visible capillary moisture in added kitchen ("spahnjenca"), no drainage, lime plaster with lacunas for paintings on the front façade;  Authors of the renovation: Vojteh Ravnikar; Ernest Milčinovič, Matjaž Bolčina, Teja Savelli						
OWNER/CONTACT	Muzej slov	enskih filmsk	ih igralcev				

NUMBER OF OBJECT IN ROR DATABASE:	2006		Status heritage:	as	/	EŠD:		
NAME OF BUILDII		Pri Maticevih						
ADDRESS AND LO	CATION:	Gor	renje pri Diva	či				
TYPE:		Pro	fane					
BUILDING (GF	SHORT DESCRIPTION OF BUILDING (GROUNDPLAN, ELEMENTS, CHRONOLOGY):			Tripartite homestead built according to the principle of successive additions: the central part is covered with škrle, a fireplace is preserved in the interior; reconstruction uncertain.				
USE (ORIGINAL):		hou	ıse					
PLATY LIMESTOI IN: (AND THEIR CONSERVATION):	STATE OF							
SPECIFIC OBSERV	ATIONS:	Renovated - the renovation was led by an architect Marko Dekleva; builder Jimmy: the roof was dismantled and rebuilt; the concrete slab was added, all the original beam were preserved						
OWNER/CONTAC	т	Mr. Mergon from Trst						

NUMBER OF OBJECT IN ROR DATABASE:	2007	Status as heritage:	Local monument	EŠD:	28321			
NAME OF BUILDING (OFFICIAL AND LOCAL):	St. Peter pa	arish Church						
ADDRESS AND LOCATION:	Povir	Povir						
TYPE:	sacral							
SHORT DESCRIPTION OF BUILDING (GROUNDPLAN, ELEMENTS, CHRONOLOGY):	triband dis	c frieze, lun dows - almo	n presbytery a nettes, rebuilt st renaissance	gothic chu	ırch (visible			
USE (ORIGINAL):	church							
PLATY LIMESTONE PRESENT IN: (AND THEIR STATE OF CONSERVATION):	Roof is completely covered with škrlje; eastern termination is plastered; year on portal 1651 (time of the superstructure of the church - baroque modernization of the gothic church roof?)							
SPECIFIC OBSERVATIONS:	bell tower was renovated by Perčič							
OWNER/CONTACT:	RKC							

NUMBER OF OBJECT IN ROR DATABASE:	2008	Status as heritage:	/	EŠD:				
NAME OF BUILDING (OFFICIAL AND LOCAL):	Homestead	l Povir 71						
ADDRESS AND LOCATION:	Povir 71	Povir 71						
TYPE:	profane							
SHORT DESCRIPTION OF BUILDING (GROUNDPLAN, ELEMENTS, CHRONOLOGY):	Quadripartite one storey homestead (additive construction)							
USE (ORIGINAL):	Residential							
PLATY LIMESTONE PRESENT IN: (AND THEIR STATE OF CONSERVATION):	The middle and the southeast part (now collapsing) covered with škrlje							
SPECIFIC OBSERVATIONS:	In the middle of the porton are chiselled a year 1849 and name »Joseph Perhauz«; the southeast part has two chimneys (high social status?!)							
QUARRY/EXTRACTION SITE IN THE AREA:	As nr. 2001	As nr. 2001						
CONTACT/OWNER:	Neighbour	across the st	treet					

NUMBER OF OBJECT IN ROR DATABASE:	2009	Status as heritage:		EŠD:			
NAME OF BUILDING (OFFICIAL AND LOCAL):	Kavalinova	Kavalinova spahnjenca					
ADDRESS AND LOCATION:	Povir						
TYPE:	profane						
SHORT DESCRIPTION OF BUILDING (GROUNDPLAN, ELEMENTS, CHRONOLOGY):	Added kitchen ("spahnjenca") of the square ground plan with hipped roof, leaned on the NW angle of the homestead; male statue on the top; entrance through wider abutment (window frame ("jerta") taken away?)						
USE (ORIGINAL):	residential						
PLATY LIMESTONE PRESENT IN: (AND THEIR STATE OF CONSERVATION):	Roof cover	ed with škrlje	2				
SPECIFIC OBSERVATIONS:	Homestead is in the phase of renovation						
QUARRY/EXTRACTION SITE IN THE AREA:	As nr. 2001						
CONTACT/OWNER:	Private ow	ner (Marko?)					

NUMBER OF OBJECT IN ROR DATABASE:	2010	Status as heritage:	Local monument	EŠD:	3942	
NAME OF BUILDING (OFFICIAL AND LOCAL):	St. Andrew f	ilial Church				
ADDRESS AND LOCATION:	Merče					
TYPE:	Sacral					
SHORT DESCRIPTION OF BUILDING (GROUNDPLAN, ELEMENTS, CHRONOLOGY):	Single-nave late gothic church, 3/8-polygonal termination of the presbytery, renovated during 1836-38; narthex added in 1779. Above western wall two-storey belfry					
USE (ORIGINAL):	church					
PLATY LIMESTONE PRESENT IN: (AND THEIR STATE OF CONSERVATION):	Central nave covered with škrlje, sacristy, narthex (referred to by Premrl the »škrle roof«)					
SPECIFIC OBSERVATIONS:	Special belfr	y (master A	nže Rojina)			
	New bells, recently blessed; new mortuary beside the cemetery					
OWNER/CONTACT:	RKC					

NUMBER OF OBJECT IN ROR DATABASE:	2011	Status as heritage:	/	EŠD:			
NAME OF BUILDING (OFFICIAL AND LOCAL):	Granary ?						
ADDRESS AND LOCATION:	Šmarje pri Se	ežani					
TYPE:	Profane	Profane					
SHORT DESCRIPTION OF BUILDING (GROUNDPLAN, ELEMENTS, CHRONOLOGY):	Single-storey granary, beside the church; external staircase						
USE (ORIGINAL):	granary						
PLATY LIMESTONE PRESENT IN: (AND THEIR STATE OF CONSERVATION):	Roof covered with škrle						
SPECIFIC OBSERVATIONS:	During the renovation an external staircase was rebuilt (poor plaster and mortar; falling down; badly constructed); structure was boosted with steel building anchors (the project is described on the sheet of paper nailed to the door)						
OWNER/CONTACT:	?						

NUMBER OF OBJECT IN ROR DATABASE:	2012	Status as heritage:	/	EŠD:		
NAME OF BUILDING (OFFICIAL AND LOCAL):	Homestead					
ADDRESS AND LOCATION:	Šmarje pri S	Sežani				
TYPE:	profane					
SHORT DESCRIPTION OF BUILDING (GROUNDPLAN, ELEMENTS, CHRONOLOGY):	Homestead, ground plan in the form of the letter L, after the additive principle; with walled farmyard (walled farmyard ("borjač") and stone portal gate ("kaluna"); on its keystone is inscription: »1853 Marko Taufer«					
USE (ORIGINAL):	house					
PLATY LIMESTONE PRESENT IN: (AND THEIR STATE OF CONSERVATION):	Roof of the eastern part is covered with škrle					
SPECIFIC OBSERVATIONS:	Roof of the eastern part is covered with škrle					
OWNER/CONTACT:	-					

NUMBER OF OBJECT IN ROR DATABASE:	2013	Status as heritage:	/	EŠD:			
NAME OF BUILDING (OFFICIAL AND LOCAL):	Pri Malnarj	Pri Malnarjevih					
ADDRESS AND LOCATION:	Križ pri Sež	ani 206					
TYPE:	profane						
SHORT DESCRIPTION OF BUILDING (GROUNDPLAN, ELEMENTS, CHRONOLOGY):	A smaller part serves as the cellar, lumber room, otherwise deserted						
USE (ORIGINAL):	residential						
PLATY LIMESTONE PRESENT IN: (AND THEIR STATE OF CONSERVATION):	Two thirds	of the homes	stead are cov	vered with šl	krle		
SPECIFIC OBSERVATIONS:	/						
QUARRY/EXTRACTION SITE IN THE AREA:	-						
CONTACT/OWNER:	?						

NUMBER OF OBJECT IN ROR DATABASE:	2014	Status as heritage:	/	EŠD:			
NAME OF BUILDING (OFFICIAL AND LOCAL):	Church	Church					
ADDRESS AND LOCATION:	Križ pri Sež	ani					
TYPE:	sacral						
SHORT DESCRIPTION OF BUILDING (GROUNDPLAN, ELEMENTS, CHRONOLOGY):	Single-nave, 3/8-polygonal termination of the presbytery and bell tower on the west; gothic windows						
USE (ORIGINAL):	church						
PLATY LIMESTONE PRESENT IN: (AND THEIR STATE OF CONSERVATION):	Roof of na	ve and of pre	esbytery				
SPECIFIC OBSERVATIONS:	Renovated bell tower and the eastern façade; on the porton the year 1689 chiselled-in; below the moulding of the sacristy a cement patching						
CONTACT/OWNER	RKC						

NUMBER OF OBJECT IN ROR DATABASE:	2015	Status as heritage:	/	EŠD:		
NAME OF BUILDING (OFFICIAL AND LOCAL):	Granary					
ADDRESS AND LOCATION:	Križ pri Sež	ani				
TYPE:	profane					
SHORT DESCRIPTION OF BUILDING (GROUNDPLAN, ELEMENTS, CHRONOLOGY):	One-storey house with external staircase					
USE (ORIGINAL):	granary					
PLATY LIMESTONE PRESENT IN: (AND THEIR STATE OF CONSERVATION):	Roof					
SPECIFIC OBSERVATIONS:	Renovated; now serves as a mortuary, interior completely modern; plastered: base moulding partially filled up with cement					
OWNER/CONTACT:	RKC				_	

NUMBER OF OBJECT IN ROR DATABASE:	2016	Status as heritage:	/	EŠD:			
NAME OF BUILDING (OFFICIAL AND LOCAL):	Pri Pilbakov	Pri Pilbakovih					
ADDRESS AND LOCATION:	Štanjel						
TYPE:	profane						
SHORT DESCRIPTION OF BUILDING (GROUNDPLAN, ELEMENTS, CHRONOLOGY):		two-storey house, built-in in the former fortified tower; loopholes visible					
USE (ORIGINAL):	homestead						
PLATY LIMESTONE PRESENT IN: (AND THEIR STATE OF CONSERVATION):	In the whole covered with škrle; pediments above the windows and doors						
SPECIFIC OBSERVATIONS:	Renovated apartment	in 2011(?)	by Perčič;	now for i	rent as an		
OWNER/CONTACT:	? 031 385 2	281					

NUMBER OF OBJECT IN ROR DATABASE:	2017	Status as heritage:	/	EŠD:		
NAME OF BUILDING (OFFICIAL AND LOCAL):	House Štan	jel 6				
ADDRESS AND LOCATION:	Štanjel 6					
TYPE:	Profane					
SHORT DESCRIPTION OF BUILDING (GROUNDPLAN, ELEMENTS, CHRONOLOGY):		made in Vol	house, rich čji grad); an	•	•	
USE (ORIGINAL):	homestead					
PLATY LIMESTONE PRESENT IN: (AND THEIR STATE OF CONSERVATION):	-					
SPECIFIC OBSERVATIONS:	-					
OWNER/CONTACT:	?					

NUMBER OF OBJECT IN ROR DATABASE:	2018	Status as heritage:	/	EŠD:			
NAME OF BUILDING (OFFICIAL AND LOCAL):	House Štan	House Štanjel 22					
ADDRESS AND LOCATION:	Štanjel 22						
TYPE:	profane						
SHORT DESCRIPTION OF BUILDING (GROUNDPLAN, ELEMENTS, CHRONOLOGY):		Two-storey house, built into the hill; added kitchen ("spahnjenca") on the upper part, viewing the street					
USE (ORIGINAL):	house						
PLATY LIMESTONE PRESENT IN: (AND THEIR STATE OF CONSERVATION):	On added k	On added kitchen ("spahnjenca")					
SPECIFIC OBSERVATIONS:	Renovated; the renovation of the added kitchen ("spahnjenca") and its roof is a case of bad practice: too slanting, škrle are insufficiently overlapping						
OWNER/CONTACT:	Family Švag	gelj					

NUMBER OF OBJECT IN ROR DATABASE:	2019	Status as heritage:	/	EŠD:			
NAME OF BUILDING (OFFICIAL AND LOCAL):	Romanesque house						
ADDRESS AND LOCATION:	Štanjel 23	Štanjel 23					
TYPE:	profane						
SHORT DESCRIPTION OF BUILDING (GROUNDPLAN, ELEMENTS, CHRONOLOGY):		, built into irna") in fron	the hill; stor t of it	ie gutter, st	one roof, a		
USE (ORIGINAL):	homestead						
PLATY LIMESTONE PRESENT IN: (AND THEIR STATE OF CONSERVATION):	Roof, pavement below?						
SPECIFIC OBSERVATIONS:	Today an ethnological exhibit						
OWNER/CONTACT:	?						

NUMBER OF OBJECT IN ROR DATABASE:	2020	Status as heritage:	Local monument	EŠD:	3832		
NAME OF BUILDING (OFFICIAL AND LOCAL):	Kapela Mai	Kapela Marije pomočnice					
ADDRESS AND LOCATION:	Lokev						
TYPE:	sacral						
SHORT DESCRIPTION OF BUILDING (GROUNDPLAN, ELEMENTS, CHRONOLOGY):	termination eastern pa axis; stairca	n of the cho rt of an aps ase in the ax	y elevated ir, gothic wind e, pointed po is of the porta n field in got	dow with tra ortal out of al, bell tower	the central within the		
USE (ORIGINAL):	chapel						
PLATY LIMESTONE PRESENT IN: (AND THEIR STATE OF CONSERVATION):	, p , p						
SPECIFIC OBSERVATIONS:	Stonemasons marks on the portal						
OWNER/CONTACT:	RKC						

NUMBER OF OBJECT IN ROR DATABASE:	2021	Status as heritage:	/	EŠD:		
NAME OF BUILDING	House Žirje	2 15				
(OFFICIAL AND LOCAL):						
ADDRESS AND LOCATION:	Žirje 15					
TYPE:	Profane					
SHORT DESCRIPTION OF BUILDING (GROUNDPLAN, ELEMENTS, CHRONOLOGY):	Two-storey house with remains of vine; stands in the angle of the piece of land; it leans to the other house, renovated building					
USE (ORIGINAL):	House					
PLATY LIMESTONE PRESENT IN: (AND THEIR STATE OF CONSERVATION):	Roof; all plates are thin					
SPECIFIC OBSERVATIONS:	The traces of the removed chimney; a hole closed with building stones, new chimney is added at the entrance; deserted (workshop?); structural damages					
CONTACT/OWNER:						

NUMBER OF OBJECT IN ROR DATABASE:	2022	Status as heritage:	/	EŠD:			
NAME OF BUILDING (OFFICIAL AND LOCAL):	Pri Kocjano	Pri Kocjanovih					
ADDRESS AND LOCATION:	Žirje 1						
TYPE:	profane						
SHORT DESCRIPTION OF BUILDING (GROUNDPLAN, ELEMENTS, CHRONOLOGY):	porton (18	Homestead, 7-partite house, walled farmyard ("borjač"), porton (1880 and initials AR – Anže Rojina?), internal porton 1790; the main house two-storey, double balcony ("gank")					
USE (ORIGINAL):	homestead	d					
PLATY LIMESTONE PRESENT IN: (AND THEIR STATE OF CONSERVATION):	Two central (easter) parts (second and third from North to South), trimmed ridge cap						
SPECIFIC OBSERVATIONS:	Renovated (on the porton 1760-1996); balcony ("gank") on the stone volute consoles						
OWNER/CONTACT:	?						

NUMBER OF OBJECT IN ROR DATABASE:	2023	Status as heritage:	/	EŠD:			
NAME OF BUILDING (OFFICIAL AND LOCAL):	Pri Polakovih						
ADDRESS AND LOCATION:	Tomaj 4						
TYPE:	profane						
SHORT DESCRIPTION OF BUILDING (GROUNDPLAN, ELEMENTS, CHRONOLOGY):		Homestead, square ground plan, walled farmyard ("borjač"), stone portal gate ("kaluna")					
USE (ORIGINAL):	homestead	d					
PLATY LIMESTONE PRESENT IN: (AND THEIR STATE OF CONSERVATION):	On the eastern wing the roof covered with škrle; brick ridge cap cemented						
SPECIFIC OBSERVATIONS:	Completely renovated, new aluminium gutter						
OWNER/CONTACT:	?						

NUMBER OF OBJECT IN ROR DATABASE:	2024	Status as heritage:	Local monument	EŠD:	3635			
NAME OF BUILDING (OFFICIAL AND LOCAL):	St. George Ch	St. George Church						
ADDRESS AND LOCATION:	Dutovlje							
TYPE:	sacral							
SHORT DESCRIPTION OF BUILDING (GROUNDPLAN, ELEMENTS, CHRONOLOGY):	Late-renaissance three-nave church with the gallery in the storey, 3/8-polygonal termination of the presbytery, qualitative stone altar in the presbytery. By the church a bell tower of an Aquileian type. Basin of Holy Water with the coat of arms of the family Della Torre and the year 1569. Third quarter of the 15th century, 1450, third quarter of the 16th century, second quarter of the 18th century, 1740. Single-nave with presbytery; sacristies on the S and N, bell tower on the W above the narthex (year 1774); baroque interior; baroque modernized interior; lodge; elevated; on the outer N wall on the base moulding year 1581; in the interior altars made by Tone Bitenc; three-band cornice							
USE (ORIGINAL):	church	US	E (CURRENT)	churc	h			
PLATY LIMESTONE PRESENT IN: (AND THEIR STATE OF CONSERVATION):	, 1, 5							
SPECIFIC OBSERVATIONS:	Renovated							
CONTACT/OWNER:	RKC							

NUMBER OF OBJECT IN ROR DATABASE:	2025	Status as heritage:	heritage	EŠD:	9131		
NAME OF BUILDING (OFFICIAL AND LOCAL):	Pri Polhovi	Pri Polhovih					
ADDRESS AND LOCATION:	Dutovlje 11	11					
TYPE:	profane						
SHORT DESCRIPTION OF BUILDING (GROUNDPLAN, ELEMENTS, CHRONOLOGY):	external st outbuilding covered w 1587. 16th century. To	d of the close aircase, the gs. Among the ith škrle; the century, 158 wo-storey bu ng building,	roof is cove e outbuildin entrance p 7, 17th cent illding is att	red with šk gs the barn ortal feature ury, 18th ce ached direc	rle, several stands out, es the year ntury, 19th tly to the		
USE (ORIGINAL):	homestead	I					
PLATY LIMESTONE PRESENT IN: (AND THEIR STATE OF CONSERVATION):	Barn roof						
SPECIFIC OBSERVATIONS:		low the winge filled up w	•	vated with	aluminium		
OWNER/CONTACT:	Artist?						

NUMBER OF OBJECT IN ROR DATABASE:	2026	Status as heritage:	As the part of the village, protected as heritage	EŠD:	9456			
NAME OF BUILDING (OFFICIAL AND LOCAL):	Pri Šekljetovi	h						
ADDRESS AND LOCATION:	Skopo 58							
TYPE:	profane							
SHORT DESCRIPTION OF BUILDING (GROUNDPLAN, ELEMENTS, CHRONOLOGY):				House with added kitchen ("spahnjenca") with hipped roof (in the SW angle), large chimney				
	house USE (CURRENT) house							
USE (ORIGINAL):	house	US	E (CURRENT)	house	<b>!</b>			
USE (ORIGINAL):  PLATY LIMESTONE PRESENT IN: (AND THEIR STATE OF CONSERVATION):			E (CURRENT) kitchen ("spah					
PLATY LIMESTONE PRESENT IN: (AND THEIR STATE OF	Building roof  VERY WELL-P  On the cou tympanon ab	and added RESERVED rtyard are obreviation	kitchen ("spah Obviously priv	njenca") vate and i	inaccessible. he western			
PLATY LIMESTONE PRESENT IN: (AND THEIR STATE OF CONSERVATION):	Building roof  VERY WELL-P  On the cou tympanon ab	and added RESERVED rtyard are obreviation	kitchen ("spah Obviously priv arranged ški "IHS".	njenca") vate and i	inaccessible. he western			

NUMBER OF OBJECT IN ROR DATABASE:	2027	Status as heritage:	/	EŠD:			
NAME OF BUILDING (OFFICIAL AND LOCAL):	House Skopo 44						
ADDRESS AND LOCATION:	Skopo 44	Skopo 44					
TYPE:	profane						
SHORT DESCRIPTION OF BUILDING (GROUNDPLAN, ELEMENTS, CHRONOLOGY):		d, built into ered with škrle			ng (by the		
USE (ORIGINAL):	house						
PLATY LIMESTONE PRESENT IN: (AND THEIR STATE OF CONSERVATION):							
SPECIFIC OBSERVATIONS:		Renovated - filled up with mortar - the stains of humidity are emerging. Case of the bad practice; added new gutter					
OWNER/CONTACT:	,						

NUMBER OF OBJECT IN ROR DATABASE:	2028	Status as heritage:		EŠD:	15974
NAME OF BUILDING (OFFICIAL AND LOCAL):	Kopriva 53				
ADDRESS AND LOCATION:	Kopriva 53				
TYPE:	profane				
SHORT DESCRIPTION OF BUILDING (GROUNDPLAN, ELEMENTS, CHRONOLOGY):			d farmyard ("l louble balcony		and stone
USE (ORIGINAL):	house	US	SE (CURRENT)	house	;
PLATY LIMESTONE PRESENT IN: (AND THEIR STATE OF CONSERVATION):	Northern wir	ng covered	with škrle		
SPECIFIC OBSERVATIONS:	Ridge covered with bricks, on the NE edge of a ridge a stone cross; (12.6. we inspected the house from outside - it wasn't accessible)				
QUARRY/EXTRACTION SITE IN THE AREA:	?				
CONTACT/OWNER:	?				

NUMBER OF OBJECT IN ROR DATABASE:	2029	Status as heritage:	As the part of the village, protected as heritage	EŠD:	15974	
NAME OF BUILDING (OFFICIAL AND LOCAL):	Kopriva 29					
ADDRESS AND LOCATION:	Kopriva 29					
TYPE:	profane					
SHORT DESCRIPTION OF BUILDING (GROUNDPLAN, ELEMENTS, CHRONOLOGY):		is a demolisl	four buildings; on ned building; on			
USE (ORIGINAL):	house					
PLATY LIMESTONE PRESENT IN: (AND THEIR STATE OF CONSERVATION):	On the roof of the middle wing are škrle: ridge covered with mortar and škrle; the central building is empty and is nowadays separated from the W part; central and E part are deserted?					
SPECIFIC OBSERVATIONS:	The remnants of the wooden beams? vine; on the eastern stone portal gate ("kaluna") an inscription: »Josef Sega 1839«					
OWNER/CONTACT:	Miro Škerlj					

NUMBER OF OBJECT IN ROR DATABASE:	2030	Status as heritage:	Heritage	EŠD:	9459		
NAME OF BUILDING (OFFICIAL AND LOCAL):	Pri Petrovih						
ADDRESS AND LOCATION:	Tupelče 4	Tupelče 4					
TYPE:	profane						
SHORT DESCRIPTION OF BUILDING (GROUNDPLAN, ELEMENTS, CHRONOLOGY):	Hugh homestead of the closed type, a property of the rich peasants with old and new residential building, covered with škrle roof. Former outbuilding altered. Homestead is encircled by the large stone wall with stone portal gate ("kaluna"). Preserved are several stonemasons' details. The last quarter of the 18th century, 1796, a second quarter of the 19th century, 1841.						
	wall.	uliu piali, i	arge meadow	vviciiii ti	ie courtyaru		
USE (ORIGINAL):	House	US	E (CURRENT)	House	e		
PLATY LIMESTONE PRESENT IN: (AND THEIR STATE OF CONSERVATION):	Central and the pedimen		ng covered wit ton	h škrle, š	íkrle also on		
SPECIFIC OBSERVATIONS:	Cornice, mad	e of bricks					
QUARRY/EXTRACTION SITE IN THE AREA:	?						
CONTACT/OWNER:	Homestead A	Nbram					

NUMBER OF OBJECT IN ROR DATABASE:	2031	Status as heritage:	As the part of the village, protected as heritage	EŠD:	23775
NAME OF BUILDING (OFFICIAL AND LOCAL):	Pri Krnelov	ih			
ADDRESS AND LOCATION:	Volčji grad	61			
TYPE:	profane				
SHORT DESCRIPTION OF BUILDING (GROUNDPLAN, ELEMENTS, CHRONOLOGY):	Homestead	d, L-shaped gr	ound plan		
USE (ORIGINAL):	house				
PLATY LIMESTONE PRESENT IN: (AND THEIR STATE OF CONSERVATION):	škrle roof, pediments of the windows consist of three layers of škrle				
SPECIFIC OBSERVATIONS:	Škrle roof; E part filled up with mortar, a roof is sagging (roofing has to be inspected); deserted? Occasionally inhabited)?				
OWNER/CONTACT:	Sonja Paho	or			

Descriptor:	Neža Čebron	Neža Čebron Lipovec						
Date:	30.7.2013	30.7.2013						
NUMBER OF OBJECT IN ROR DATABASE:	2032 Status as heritage: Mational monument EŠD: 9111							
NAME OF BUILDING (OFFICIAL AND LOCAL):	Pr' Vncku							
ADDRESS AND LOCATION:	Matavun 15,	Divača						
TYPE:	profane							
SHORT DESCRIPTION OF BUILDING (GROUNDPLAN, ELEMENTS, CHRONOLOGY):	4/6-polygona ("spahnjenca chimney is a circumferenc	I termina "), in the also 4/6-p e); on the	artite, additive pation of the interior a fire olygonal termindow for year 1883/5 Z	add eplace is nated (š rame ("j	ed kitchen preserved; krle on the			
USE (ORIGINAL):	house	US	SE (CURRENT)	house	2			
PLATY LIMESTONE PRESENT IN: (AND THEIR STATE OF CONSERVATION):		e of the ch	chen ("spahnje imney; škrle on njenca")					
SPECIFIC OBSERVATIONS:	Stonelayers; moss	breaking	especially on	the east	); otherwise			
QUARRY/EXTRACTION SITE IN THE AREA:	?							
CONTACT/OWNER:	Owner Matja	ž Škrlj; in t	he rent Emil&Ta	amara				

NUMBER OF OBJECT IN ROR DATABASE:	2033	Status as heritage:	National monument	EŠD:	9107			
NAME OF BUILDING (OFFICIAL AND LOCAL):	Pr' Betanci	Pr' Betanci						
ADDRESS AND LOCATION:	Betanja 2,	Betanja 2, Divača						
TYPE:	profane							
SHORT DESCRIPTION OF BUILDING (GROUNDPLAN, ELEMENTS, CHRONOLOGY):	Karstic homestead; bipartite, added kitchen ("spahnjenca"), walled farmyard ("borjač") and stone portal gate ("kaluna"); year 1605 on the NW window							
USE (ORIGINAL):	house							
PLATY LIMESTONE PRESENT IN: (AND THEIR STATE OF CONSERVATION):	On the northern wing of a homestead a roof covered with skrle (in that lower part a window with the year 1605); roof of added kitchen ("spahnjenca") (gentlier sloping)							
SPECIFIC OBSERVATIONS:	Approximately 10 years ago it was renovated; larger roof partially filled up with cement and mortar; moss, irregular terminations; roof of added kitchen ("spahnjenca") reconstructed?							
OWNER/CONTACT:	Cerkvenik;	tourist farm;	inhabited					

NUMBER OF OBJECT IN ROR DATABASE:	2034	Status heritag		national monument	EŠD:	9120	
NAME OF BUILDING (OFFICIAL AND LOCAL):	Jakopin barn						
ADDRESS AND LOCATION:	Škocjan 7						
TYPE:	Profane						
SHORT DESCRIPTION OF BUILDING (GROUNDPLAN, ELEMENTS, CHRONOLOGY):	Barn; single room; reconstructed in 1999; once with straw roof and covered with škrle above the pediment walls						
USE (ORIGINAL):	barn		USE	(CURRENT):	exhibi	tion hall	
PLATY LIMESTONE PRESENT IN: (AND THEIR STATE OF CONSERVATION):	Roofing abov	e the pe	edim	nent walls			
SPECIFIC OBSERVATIONS:	Building completely reconstructed, following the original plan; new walls and construction joints thickly filled up						
QUARRY/EXTRACTION SITE IN THE AREA:	?						
CONTACT/OWNER:	Park Škocjan	Caves				_	

NUMBER OF OBJECT IN ROR DATABASE:	2035	Status as heritage:	/	EŠD:			
NAME OF BUILDING (OFFICIAL AND LOCAL):	Pr' B'zkovih	Pr' B'zkovih					
ADDRESS AND LOCATION:	Naklo 14, E	)ivača					
TYPE:	profane						
SHORT DESCRIPTION OF BUILDING (GROUNDPLAN, ELEMENTS, CHRONOLOGY):	eastern an view – obv angled roo	d of the clogle wing covering to the country an extending the country and the work of the	ered with skr ension (in th window fra	le – angled e interior in mes ("jerta	in the plan the wall in s"); cistern		
USE (ORIGINAL):	homestead						
PLATY LIMESTONE PRESENT IN: (AND THEIR STATE OF CONSERVATION):	Southern angle wing and pediments of the windows are covered with škrle; in 2012 were renovated exterior and roof (led by Perčič) — stone ridge and few škrle were changed; on the façade preserved inscription field; well-preserved.						
SPECIFIC OBSERVATIONS:	The house is inhabited by a family for centuries; rich family history (from here Mahorčič, explorer of the caves and the mayor of Naklo); škrle wing served as a granary on the left and as a kitchen and a room for conserving and smoking the meat on the right side.						
OWNER/CONTACT:	Family Mal	norčič					

NUMBER OF OBJECT IN ROR DATABASE:	2036	Status as heritage:	/	EŠD:		
NAME OF BUILDING	Homestead					
(OFFICIAL AND LOCAL):						
ADDRESS AND LOCATION:	Vrhovlje 19	)				
TYPE:	Profane					
SHORT DESCRIPTION OF BUILDING (GROUNDPLAN, ELEMENTS, CHRONOLOGY):	Homestead – additive principle; two wings (separated) with škrle-roof					
USE (ORIGINAL):	Homestead	d				
PLATY LIMESTONE PRESENT IN: (AND THEIR STATE OF CONSERVATION):	Two separated units of the circumference building structure covered with škrle					
SPECIFIC OBSERVATIONS:	(in the whole village there are a lot of buildings built no more than some 20cm apart)					
OWNER/CONTACT:	Consortiun	n of Karst win	emakers; Fa	rmstead Pri (	Čotovih	

NUMBER OF OBJECT IN ROR DATABASE:	2037	Status as heritage:	/	EŠD:			
NAME OF BUILDING (OFFICIAL AND LOCAL):	Homestead						
ADDRESS AND LOCATION:	Vrhovlje 13	3					
TYPE:	Profane						
SHORT DESCRIPTION OF BUILDING (GROUNDPLAN, ELEMENTS, CHRONOLOGY):	Homestead of the closed type; walled farmyard ("borjač"), stone portal gate ("kaluna") (rich decoration – Volčji grad?), two niches are arranged by kaluna; stone brackets are used for the gutter						
USE (ORIGINAL):	Homestead						
PLATY LIMESTONE PRESENT IN: (AND THEIR STATE OF CONSERVATION):	Western wing covered with škrle; above the one in platy limestone are pediments						
SPECIFIC OBSERVATIONS:	Ridge filled up with mortar						
QUARRY/EXTRACTION SITE IN THE AREA:	?						
CONTACT/OWNER:	Ravbar						

NUMBER OF OBJECT IN ROR DATABASE:	2038	Status as heritage:	/	EŠD:		
NAME OF BUILDING (OFFICIAL AND LOCAL):	Homestead					
ADDRESS AND LOCATION:	Vrhovlje 31	L				
TYPE:	Profane					
SHORT DESCRIPTION OF BUILDING (GROUNDPLAN, ELEMENTS, CHRONOLOGY):	Homestead, L-shaped ground plan; walled farmyard ("borjač"), stone portal gate ("kaluna") (rich decoration and an inscription 1852 Anderi Sherperle)					
USE (ORIGINAL):	Homestead					
PLATY LIMESTONE PRESENT IN: (AND THEIR STATE OF CONSERVATION):	Northern wing covered with škrle (at least two stories, one small window)					
SPECIFIC OBSERVATIONS:	Ridge filled up with cement mortar					
OWNER/CONTACT:	Vidmar					

Descriptor:	Neža Čebron Lipovec						
Date:	31.7.2013	31.7.2013					
NUMBER OF OBJECT IN ROR DATABASE:	2039 Status as / EŠD: heritage:						
NAME OF BUILDING (OFFICIAL AND LOCAL):	Homestead						
ADDRESS AND LOCATION:	Voglje 12						
TYPE:	Profane						
SHORT DESCRIPTION OF BUILDING (GROUNDPLAN, ELEMENTS, CHRONOLOGY):	Homestead – building in the line; one wing in the East (?) - building is renovated, škrle-roof well preserved						
USE (ORIGINAL):	Homestead						
PLATY LIMESTONE PRESENT IN: (AND THEIR STATE OF CONSERVATION):	Part of the line covered with škrle – House old, is sagging, has beams; ridge, consists of cement and škrle						
SPECIFIC OBSERVATIONS:							
CONTACT/OWNER:							

NUMBER OF OBJECT IN ROR DATABASE:	2040	Status as heritage:	/	EŠD:			
NAME OF BUILDING (OFFICIAL AND LOCAL):	Pri S'kčevih						
ADDRESS AND LOCATION:	Voglje 3						
TYPE:	Profana						
SHORT DESCRIPTION OF BUILDING (GROUNDPLAN, ELEMENTS, CHRONOLOGY):	Karstic homestead of the closed type; additive principle; consists of four units; the easternmost unit is covered with škrle; walled farmyard ("borjač") and richly decorated stone portal gate ("kaluna") (inscription Janes Raubar MXCCCLXI); stone brackets for gutter						
USE (ORIGINAL):	homestead						
PLATY LIMESTONE PRESENT IN: (AND THEIR STATE OF CONSERVATION):	One out of four units covered with škrle; storey building, window frames ("jertas"); window pediments; plastered						
SPECIFIC OBSERVATIONS:							
OWNER/CONTACT:							

NUMBER OF OBJECT IN ROR DATABASE:	2041	Status as heritage:	/	EŠD:				
NAME OF BUILDING (OFFICIAL AND LOCAL):	Homestead	Homestead						
ADDRESS AND LOCATION:	Kazlje 13							
TYPE:	Profane							
SHORT DESCRIPTION OF BUILDING (GROUNDPLAN, ELEMENTS, CHRONOLOGY):	Karstic homestead, L-shaped ground plan; walled farmyard ("borjač"), stone portal gate ("kaluna"), gallery ("baladur") (renovated); interesting chimney; eastern wing covered with škrle							
USE (ORIGINAL):	homestead							
PLATY LIMESTONE PRESENT IN: (AND THEIR STATE OF CONSERVATION):	Eastern wing covered with škrle; (unique?) tympanon – tripartite roof (incorporated added kitchen ("spahnjenca")?), 3 vents							
SPECIFIC OBSERVATIONS:	Renovated, ridge and corners filled up with mortar; plastered							
OWNER/CONTACT:	?	?						

NUMBER OF OBJECT IN ROR DATABASE:	2042	Status as heritage:	/	EŠD:			
NAME OF BUILDING	Homestead	d					
(OFFICIAL AND LOCAL):							
ADDRESS AND LOCATION:	Kazlje 10						
TYPE:	Profana						
SHORT DESCRIPTION OF BUILDING (GROUNDPLAN, ELEMENTS, CHRONOLOGY):	Karstic homestead, house in the line, new extension, new concrete circumference of walled farmyard ("borjač") and minimalistic, modern entrance; the other parts of the building covered with bricks						
USE (ORIGINAL):	Homestead						
PLATY LIMESTONE PRESENT IN: (AND THEIR STATE OF CONSERVATION):	Central part of the line covered with škrle, higher loading gauge, gallery ("baladur") and the rest covered with bricks; that part of the building is plastered						
SPECIFIC OBSERVATIONS:	Completely renovated, roof is sagging (old?), 2 vents, newer chimney, ridge made of mortar and skrile (structure? Interior?)						
OWNER/CONTACT:	3	?					

NUMBER OF OBJECT IN ROR DATABASE:	2043	Status as heritage:	/	EŠD:			
NAME OF BUILDING (OFFICIAL AND LOCAL):	Pr' Kudrovi	Pr' Kudrovih					
ADDRESS AND LOCATION:	Kazlje 38						
TYPE:	Profane						
SHORT DESCRIPTION OF BUILDING (GROUNDPLAN, ELEMENTS, CHRONOLOGY):	Karstic homestead of the opened type, C-shaped ground plan						
USE (ORIGINAL):	Homestead						
PLATY LIMESTONE PRESENT IN: (AND THEIR STATE OF CONSERVATION):	Two units covered with škrle, one of them is decaying, overgrown with vegetation; the other is a barn						
SPECIFIC OBSERVATIONS:	Barn roof apparently elevated > visible is the loading gauge of the former. Height difference filled up with škrle; on the second pediment wall, on the height of the lower part of the roof »sill« made of škrle						
OWNER/CONTACT:							

NUMBER OF OBJECT IN ROR DATABASE:	2044	Status as heritage:	/	EŠD:			
NAME OF BUILDING (OFFICIAL AND LOCAL):	Pr' Golanto	Pr' Golantovih					
ADDRESS AND LOCATION:	Kazlje 46						
TYPE:	Profane						
SHORT DESCRIPTION OF BUILDING (GROUNDPLAN, ELEMENTS, CHRONOLOGY):	Karstic homestead of the closed type; stone portal gate ("kaluna") with a year, cistern ("štirna"), wings with gallery ("baladur") on the profiled consoles; NW wing with škrleroof with "hramc"; painted below the baladur; more years are chiselled, spolium of the window in the economic wing with a year 1606 (?)						
USE (ORIGINAL):	homestead						
PLATY LIMESTONE PRESENT IN: (AND THEIR STATE OF CONSERVATION):	NW wing of the complex (house with "hramc"); once served as a granary, later upper floor as a dormitory of the brothers, now again granary, storage; window pediments in that part						
SPECIFIC OBSERVATIONS:	Roof is well-preserved, some škrle stone layers on the western (northern?) side						
CONTACT/OWNER:	Lojze Vran				-		

NUMBER OF OBJECT IN ROR DATABASE:	2045	Status as heritage:	/	EŠD:				
NAME OF BUILDING (OFFICIAL AND LOCAL):	Pr' Urbanič	Pr' Urbaničevih						
ADDRESS AND LOCATION:	Filipčje Brd	o 2						
TYPE:	Profane							
SHORT DESCRIPTION OF BUILDING (GROUNDPLAN, ELEMENTS, CHRONOLOGY):	Karstic homestead of the closed type; stone portal gate ("kaluna" ) with škrle pediment; the largest part of the complex is newer (1980')							
USE (ORIGINAL):	Homestead							
PLATY LIMESTONE PRESENT IN: (AND THEIR STATE OF CONSERVATION):	Western part of a complex covered with škrle; stone portal gate ("kaluna") covered with škrle							
SPECIFIC OBSERVATIONS:								
OWNER/CONTACT:	Farmstead Škrlj							